

Mr. Fujimoto:

In order for processing of this application (FCC ID: THZ-PRO9160100) to continue, the following issue(s) will have to be addressed:

- 1) Please provide a correction of the duty cycle plots. During the count, it was found that only 22 small pulses exist instead 23 small pulses.
- 2) Please include the clock speeds of the data of all the data buses shown on the block diagram.
- 3) Please provide a more descriptive explanation of the operation of the EUT.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Please upload responses and/or exhibits to the electronic filing website. Your correspondence number is THZ-PRO9160100-1

Best Regards,

Mike Christensen
Evaluator
Compatible Electronics TCB
Phone: 714-579-0500
Fax: 714-579-1850
www.celectronics.com