

Helen Zhao

Subject: FW: Honda Access Corp. , FCC ID: TIC-RS06AU, Assessment NO.: AN05T5089, Notice#1



Setup 0513638-1 FCC
Photos(revised).pdf 15.231 Report(r...

Hi Helen,

Pls see answer below.

Question #1: The test report indicates that no cable no support equipment was ever used during the test, but the Setup photos show the device was connected with the cables (DC power source might be used). Please update the test report.

<answer>report is revised. setup photos is also revised due page number changed.

Quesiton #2: Parts List is submitted as one of technical documents, but it is not listed on confidentiality letter. Please confirm Parts list is OK for public inspection.

<answer>client decided NOT to submit parts list to TCB.

Thanks,

Claire