

Response to TCB Findings

Test setup photos show the device without cover. Please clarify the reason

The reason the cover was off, was that we were using onboard connectors to put the device into different test modes. The cover is plastic, so the radiated readings are worst case.