




802.11ax40

Channel 3: 5965MHz




Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03

802.11ax40

Channel 91: 6405MHz




Date: 19.MAR.2025 18:57:29




Date: 19.MAR.2025 21:23:44

802.11ax80

Channel 7: 5985MHz




Date: 19.MAR.2025 18:30:18





Date: 19.MAR.2025 21:35:16

Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03








Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03








Report No.: AAEMT/RF/250131-01-03




802.11be40

Channel 3: 5965MHz




Date: 17.MAR.2025 18:13:53




Date: 19.MAR.2025 23:41:58

Report No.: AAEMT/RF/250131-01-03





Report No.: AAEMT/RF/250131-01-03





Report No.: AAEMT/RF/250131-01-03

802.11be80

Channel 7: 5985MHz










802.11be160

Channel 15: 6025MHz




802.11be160


Channel 47: 6185MHz



Date: 17.MAR.2025 23:59:17





Date: 20.MAR.2025 00:25:40





802.11be320

Channel 63: 6265MHz




802.11ax20


Channel 97: 6435MHz



Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03




802.11ax40

Channel 99: 6445MHz




Date: 19.MAR.2025 19:02:32




Date: 19.MAR.2025 21:24:27

Report No.: AAEMT/RF/250131-01-03





Report No.: AAEMT/RF/250131-01-03



Report No.: AAEMT/RF/250131-01-03

802.11ax80


Channel 103: 6465MHz




Report No.: AAEMT/RF/250131-01-03

802.11be20

Channel 97: 6435MHz





Date: 17.MAR.2025 17:39:04



Date: 19.MAR.2025 23:43:44

Report No.: AAEMT/RF/250131-01-03









Report No.: AAEMT/RF/250131-01-03


802.11be40

Channel 99: 6445MHz











Report No.: AAEMT/RF/250131-01-03

802.11ax20


Channel 117: 6535MHz





Date: 19.MAR.2025 19:27:01



Date: 19.MAR.2025 21:15:27





Report No.: AAEMT/RF/250131-01-03





802.11ax40

Channel 123: 6565MHz



Report No.: AAEMT/RF/250131-01-03








Report No.: AAEMT/RF/250131-01-03


802.11ax80

Channel 135: 6625MHz







Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03

802.11ax160


Channel 143: 6665MHz



Report No.: AAEMT/RF/250131-01-03



Report No.: AAEMT/RF/250131-01-03



Report No.: AAEMT/RF/250131-01-03

