

Icoms Detections SA
Avenue Einstein 11/B
B-1348 Louvain-la-Neuve
Belgium

T +32 10 45 41 02
F +32 10 45 04 61

info@icomsdetections.com
www.icomsdetections.com

9 March 2020

To whom it may concern:


HVIN: TMS-SA

Re: FCC ID: TRQ-TMSSA

Grant Date: 12/18/2019

This is a justification letter to justify why the following exhibits need to be revised on the FCC site.

- (a) Operational Description of Transceiver. Attached is the corrected exhibit.
- (b) Schematics uploaded were from a different model. Attached are the correct exhibit.
- (c) Internal photos uploaded were from a different model. Attached are the correct photos..
- (d) BOM uploaded were from a different model. Attached are the correct exhibit



Etienne Van den Bogaert

Managing Director

Icoms Detections SA

Email: e.vandenbogaert@icomsdetections.com

Tel: +32 10 45 41 02 ext 222