

## **Tune-up Procedure**

Each unit is tested during production for functionality against the pass/fail criteria. The unit is then given pass/fail status based on the measured parameters. The pass/fail threshold is determined by engineering during product development. Compliant samples continue through production and non-compliant units are removed.