

1.5. EUT Exercise Software

Test Mode		Mode 1: Slide Show
1		Setup EUT and Monitor as shown on 1.4.
2		Play REC file (black loop).
3		Turn on the power.
4		Select play key.
5		Press MENU.
6		Press left key to select play OK.
7		Select START OK.
8		Show word of slide show on LCD display.
9		Test.

Test Mode		Mode 2: REC
1		Setup EUT and Monitor as shown on 1.4.
2		The lens of EUT was covered with black tape.
3		Turn on the power of all equipment.
4		Press REC key.
5		Save black file.

Test Mode		Mode 3: USB LCD on
1		Setup EUT and PC as shown on 1.4.
2		Loop transmit REC file with USB cable.
3		Turn on the power.
4		Write DSC file to PC for example.

Test Mode		Mode 4: Preview
1		Setup EUT and Monitor as shown on 1.4.
2		The lens of EUT was covered with black tape.
3		Turn on the power of all equipment.
4		Select capture preview mode.
5		Test.