



**UL CCS**

47173 Benicia Street, Fremont, CA 94538  
Tel: 510.771.1000 | Fax: 510.661.0888 | [www.cssemc.com](http://www.cssemc.com)

Federal Communication Commissions  
7435 Oakland Mills Road  
Columbia MD 21046

Subject: Request FCC to replace previous submitted user manual

Ref: Applicant: Realtek Semiconductor Corp.

FCC ID: TX2-RTL8191SE

TCB Assessment no.: AN10T0170

Grant date: 3/15/2010

To Whom It May Concern:

CCS-TCB issued the grant on 3/15/2010; during the internal audit process, the agent found that previous version of RF test report was mistakenly uploaded. Pursuant to KDB 546630 D01 TCB Supersede Procedures, CCS-TCB will supersede the file of RF test report uploaded in 03/15/2010 from FCC database and replaced by the attached file "RTL8191SE RF Test Report Revised 0402".

Thank you.

Best Regards,

*Mike Kuo*

---

Mike Kuo.  
Compliance Certification Services  
04/06/ 2010

an Underwriters Laboratories company

