

<p>MODEL: CONNECT-FLX</p> <p>WEEKLY TESTING IS REQUIRED TO ENSURE PROPER OPERATION OF THE SYSTEM.</p> <p>DO NOT CONNECT TO A RECEPTACLE CONTROLLED BY A SWITCH. N'APAS SE CONNECTER A UNE PRISE CONTRÔLÉE PAR UN INTERRUPTEUR.</p> <p>THIS UNIT IS TO BE CHECKED BY A QUALIFIED TECHNICIAN AT LEAST ONCE EVERY THREE YEARS.</p> <p>RECHARGEABLE BATTERY PACK TO BE REPLACED EVERY 6 YEARS UNDER NORMAL OPERATING CONDITIONS.</p> <p>REPLACEMENT RECHARGEABLE BATTERY: 6VDC 2.5Ah NiMH PART#: RE029</p> <p>POWER SUPPLY: 12VDC, 1A INPUT: 100-240VAC, 50/60 Hz PART#: RE012-08W</p> <p>Atula, 428 Minnesota Street, Suite 300, St. Paul, MN 55101 MADE IN BULGARIA</p> <p>48-10297-00 RevA</p>	<p>This equipment should be installed in accordance with Chapter 29 of the National Fire Alarm and Signaling Code, ANSI/NFPA 72, (National Fire Protection Association, Batterymarch Park, Quincy, MA 02269)</p> <p>PRINTED INFORMATION DESCRIBING PROPER INSTALLATION, OPERATION, TESTING, MAINTENANCE, EVACUATION PLANNING, AND REPAIR SERVICE IS TO BE PROVIDED WITH THIS EQUIPMENT. SEE USER'S GUIDE FOR COMPLETE OPERATION: 47-00041-00 RevA</p> <p>FCC ID: U5X-CFLXRF; IC: 8310A-CFLXRF Contains FCC ID: R7ME310G1WW Contains IC: E131A-ME310G1WW Contains FCC ID: 2AC7Z-ESP32WROOM32E Contains IC: 21098-ESPWROOM32E</p>
---	---

FCC ID: USX-CFLXR; IC: 8310A-CFLXR FCC ID: USX-CFLXZ; IC: 8310A-CFLXZ Contains FCC ID: R7ME310G1WW Contains IC: 5131A-ME310G1WW Contains FCC ID: 2AC7Z-ESP32WROOM32E Contains IC: 2109B-ESPWROOM32E	
--	--

--	--