

Date: March 24, 2008  
Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, MD 21046

Attn: OET Dept.

FCC ID: UK9POL9D

Applicant: Mobinnova Corp.

Form 731 Confirmation Number: EA414594

Correspondence Reference Number: 34999

**Dear Examiner,**

- 1) Test plots for 2450 MHZ as stand alone plots are not relevant and not to be filed, please remove these from the application.

Reply: The plots for 2450 MHz had been removed from HAC test report. And please also dismiss the file (ULTIMATE 8502 HAC for CD2450V3-SN1026).

- 2) As of today, ANSI 63.19-2007 is not accepted as a test procedure. ANSI 63.19-2006 is the currently accepted standard. Please adjust filing appropriately.

Reply: The testing report for HAC had been re-tested according to ANSI 63.19-2006, please see the revised test report and test plot.

- 3) Please explain all co-location and co-transmission modes and how they fit into test procedures. When filing the test results for a subset of operational modes, the documentation must list all operational modes of the device that may effect compliance with FCC rules. This includes user selectable options, as well as the modes that are used to implement the service capabilities that may be invisible to a user. For each mode listed the applicant must justify why it was or was not tested, and how it ensures compliance if not tested. The documentation should be submitted in the HAC report.

Reply: The test modes are GSM and WCDMA with the worst channel of Turn-ON WLAN and Bluetooth to transmit simultaneously.

- 4) Please submit a description of the distance used between reference and measurement plan. What procedure is being followed, 10 or 15 mm? This is difficult to perceive from the picture.

Reply: The distance used is 10mm according to ANSI 63.19-2006.

- 5) The confidentiality asked the Part List and Tune up procedure to be held confidential. You asked in the email "Also, please have the Part List and Tune up procedure to be short-term confidentiality." Please explain.

Reply: Sorry for the mistake, please note that Part list and tune up procedure is under long-term confidence. Please have the revised confidentiality letter.

If you have any questions regarding this application, please feel free to contact me.

Sincerely yours,

Amanda Wu  
e-mail: [amanda.wu@tw.ccsemc.com](mailto:amanda.wu@tw.ccsemc.com)  
Compliance Certification Services.