



Appendix D. SAR Test Setup Photos

Body-worn Exposure Condition



Front with Holster at 0 mm



Right Side with Holster at 0 mm



Left Side with Holster at 0 mm

Extremity Exposure Condition




Back at 0 mm



PD Exposure Condition



Front with Holster at 2 mm



Right Side with Holster at 2 mm



Left Side with Holster at 2 mm



Back at 2 mm