

Appendix D. SAR Test Setup Photos


Body Exposure Condition



Front with Battery 1 at 10 mm



Front with Battery 1/Wrist Mount at 10 mm




Back with Battery 1 at 10 mm



Back with Battery 1/Wrist Mount at 0 mm



Back with Battery 1/Hip Mount 1 at 0 mm




Right Side with Battery 1 at 10 mm




Bottom Side with Battery 1 at 10 mm



Top Side with Battery 1 at 10 mm




Front with Battery 2 at 10 mm



Back with Battery 2 at 10 mm




Bottom Side with Battery 2 at 10 mm




Right Side with Battery 2 at 10 mm


Extremity Exposure Condition



Front with Battery 1 at 0 mm




Back with Battery 1 at 0 mm




Right Side with Battery 1 at 0 mm



Bottom Side with Battery 1 at 0 mm




Top Side with Battery 1 at 0 mm



Back with Battery 2 at 0 mm




Bottom Side with Battery 2 at 0 mm




Right Side with Battery 2 at 0 mm


PD Exposure Condition




Front with Battery 1 at 2 mm




Back with Battery 1 at 2 mm




Right Side with Battery 1 at 2 mm



Top Side with Battery 1 at 2 mm



Bottom Side with Battery 1 at 2 mm



Bottom Side with Battery 2 at 2 mm