

Date: August 9, 2007

**Compliance Certification Services****Certification Division****561F Monterey Road****Morgan Hill, CA 95037****To.** whom it may concern:

We, Wintelecom Inc would like to declare that this device, FCC ID: VIMWA500SU does not operate at 5150-5350 MHz and support turbo mode, because we block these functions by firmware. So user cannot control and operate above frequency and mode by software.

Sincerely Yours,

**Soon-Beom Kwon / Assistant Manager****Wintelecom Inc.****TEL: +82-31-744-0631****FAX: +82-31-744-0649**