



### **APPENDIX 3: Photographs of test setup**

#### **Conducted Emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**


**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

### Radiated Spurious Emission



**Photo 1**




**Photo 2**

### Worst Case Position


Above 1GHz  
(Horizontal: X-axis/ Vertical:Z-axis)

Below 1GHz  
(Horizontal: X-axis/ Vertical:X-axis)


X-axis




Y-axis




Z-axis



### Antenna Terminal Conducted Tests



**Photo 1**



**Photo 2**

**End of Report**