

Lucy Tsai

From: jill.shiau [jill.shiau@tw.ccsemc.com] on behalf of application [application@tw.ccsemc.com]
Sent: Thursday, November 29, 2007 12:57 AM
To: Lucy Tsai
Cc: jill.shiau
Subject: Re:FW: Hwa Yao Technologies Co., Ltd., FCC ID: VQ2-USB-2450-01-0, Assessment NO.: AN07T7391, Notice#1
Attachments: USB-2450-XX ConfidentialLetter1129.pdf; USB-2450-XX IDLabel&Location1129.pdf; USB-2450-XX SetupPhotos1129.pdf; USB-2450-XX TestReport1129.pdf

Hi Lucy:

Please address following issues.

Q#1: The FCC ID listed doesn't comply with Part 2.925 and 2.926. Per Part 2.926, FCC ID can't exceed 17 Arabic numerals, including 3 Arabic numerals of grantee code. Please revise all related documents.

Ans1# The new FCC ID: VQ2-USB2450-01-03, and the all related documents has been revised.

Q#2: Per antenna specification, the antenna gain is 7dBi and per 15.247, if transmitting antennas of directional gain greater than 6 dBi are used, the conducted output power from the intentional radiator shall be reduced by the amount in dB that the directional gain of the antenna exceeds 6 dBi. Please revise the limit of RF output power listed in test report.

Ans2# Revised the limit of RF output power, see page 15 of test report.

Q#3: According to internal photos, an embedded PCB antenna is used, however, there are no technical documents has addressed this antenna. Please address.

Ans3# The PCB antenna has been disabled.

"Lucy Tsai"

<jucy.tsai@ccsemc.com>

收件人 : "application" <application@tw.ccsemc.com>

副本抄送 :

2007/11/28 04:21 PM

主旨 : FW: Hwa Yao Technologies Co., Ltd., FCC ID: VQ2-USB-2450-01-0, Assessment NO.: AN07T7391, Notice#1

Hi Jill,

Please address following issues.

Q#1: The FCC ID listed doesn't comply with Part 2.925 and 2.926. Per Part 2.926, FCC ID can't exceed 17 Arabic numerals, including 3 Arabic numerals of grantee code. Please revise all related documents.

Q#2: Per antenna specification, the antenna gain is 7dBi and per 15.247, if transmitting antennas of directional gain greater than 6 dBi are used, the conducted output power from the intentional radiator shall be reduced by the amount in dB that the directional gain of the antenna exceeds 6 dBi. Please revise the limit of RF output power listed in test report.

Q#3: According to internal photos, an embedded PCB antenna is used, however, there are no technical documents has addressed this antenna. Please address.

Best Regards,

Lucy

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.