



Lat-Lon LLC, A Geotab Company  
2300 South Jason St.  
Denver, CO 80223, USA

FEB 01, 2022

**Subject: Declaration of MX5000 CATM RevH HW Changes**

By means of this letter, **Lat-Lon LLC.** declares that the Lat-Lon MX5000\_4GPLUS\_RevH Revision **H**, has the following hardware component changes for the purpose of PTCRB/FCC/ISED review:

| Component Designator                  | Reason for Change                                                                                                |
|---------------------------------------|------------------------------------------------------------------------------------------------------------------|
| FID1, FID2, FID3                      | Added 3 fiducials on top layer.                                                                                  |
| FID4, FID5, FID6                      | Added 3 fiducials on bottom layer                                                                                |
| StaicVia39, StaicVia44,<br>StaicVia45 | Moved 3 vias for distances less than 1.5mm to allow space for FID6 fiducial on the bottom layer                  |
| NET72                                 | Moved the trace of net (2.5/3.3V Interface voltage Selection) around the FID1 location on the top layer .        |
| ~RESET                                | Moved 5mm section of Trace of the Net ~RESET for 1 millimeter to allow space for FID1 fiducial on the top layer. |

Sincerely,

[Joe Deppong](#)

Senior Hardware Engineer