

**HCT Co., Ltd.**

74, Seoicheon-ro 578beon-gil, Majang-myeon, Icheon-si, Gyeonggi-do, 17383 KOREA

Tel. +82 31 634 6300 Fax. +82 31 645 6401

Appendix A: Test Setup Photo

FCC ID
W6UER4040


File No.
HCT-RF-2206-FC023-P

REVISION HISTORY

The revision history for this document is shown in table.


Revision No.	Date of Issue	Description
0	June 17, 2022	Initial Release
1	June 28, 2022	- Modified radiated test setup photos.

1. Conducted Test Setup Photo




2. Radiated Test Setup Photo(Antenna Mast : above 1 GHz Horizontal)


External_L1




External_L2



Internal_L1




Internal_L2




3. Radiated Test Setup Photo(Antenna Mast : above 1 GHz Vertical)


External_L1




External_L2



Internal_L1




Internal_L2




4. Radiated Test Setup Photo(Antenna Mast : below 1 GHz Horizontal)


External_L1




External_L2



Internal_L1




Internal_L2




5. Radiated Test Setup Photo(Antenna Mast : below 1 GHz Vertical)


External_L1




External_L2



Internal_L1



Internal_L2



End of report