



**ORPAK Systems Ltd.**, 31 Lechi St, P.O.Box 1461 Bnei Brak 51114 Israel  
Tel: 972-3-577-6868 • Fax: 972-3-579-6310 • [www.orpak.com](http://www.orpak.com)

Date: June 9, 2016

attn: Reviewing Engineer  
Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

To Whom It May Concern:


The NNR-T + Coil #7, FCC ID: W8F800960060 and label is so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3) "This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

Sincerely,



Yair Elul,  
Engineering Manager