


Test setup photographs
AC Line Conducted Emissions




Rogers Labs, Inc.
4405 W. 259th Terr
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
Model: CFL Sprint MXM MkX Repeater
Test: 200910
Test to: 47CFR, 15.407, RSS-247
File: 58F2DMXMRX Short Term Conf TSup

S/N's: 331690100444/331700100445
FCC ID: W9Z-58F2DMXMRX
IC: 8855A-58F2DMXMRX
Date: November 25, 2020
Page 1 of 4

Radiated Emissions



Rogers Labs, Inc.
4405 W. 259th Terr
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
Model: CFL Sprint MXM MkX Repeater
Test: 200910
Test to: 47CFR, 15.407, RSS-247
File: 58F2DMXMRX Short Term Conf TSup


S/N's: 331690100444/331700100445
FCC ID: W9Z-58F2DMXMRX
IC: 8855A-58F2DMXMRX
Date: November 25, 2020
Page 2 of 4



Rogers Labs, Inc.
4405 W. 259th Terr
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
Model: CFL Sprint MXM MkX Repeater
Test: 200910
Test to: 47CFR, 15.407, RSS-247
File: 58F2DMXMRX Short Term Conf TSup

S/N's: 331690100444/331700100445
FCC ID: W9Z-58F2DMXMRX
IC: 8855A-58F2DMXMRX
Date: November 25, 2020
Page 3 of 4



Rogers Labs, Inc.
4405 W. 259th Terr
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
Model: CFL Sprint MXM MkX Repeater
Test: 200910
Test to: 47CFR, 15.407, RSS-247
File: 58F2DMXMRX Short Term Conf TSup

S/N's: 331690100444/331700100445
FCC ID: W9Z-58F2DMXMRX
IC: 8855A-58F2DMXMRX
Date: November 25, 2020
Page 4 of 4