















ANT3_802.11n_HT20_UNII 1






ANT3_802.11n_HT20_UNII 2A






ANT3_802.11n_HT20_UNII 2C






ANT3_802.11n_HT20_UNII 3






ANT4_802.11n_HT20_UNII 1






ANT4_802.11n_HT20_UNII 2A






ANT4_802.11n_HT20_UNII 2C






ANT4_802.11n_HT20_UNII 3






ANT1_802.11ac_VHT20_UNII 1






ANT1_802.11ac_VHT20_UNII 2A






ANT1_802.11ac_VHT20_UNII 2C






ANT1_802.11ac_VHT20_UNII 3






ANT2_802.11ac_VHT20_UNII 1



ANT2_802.11ac_VHT20_UNII 2A





ANT2_802.11ac_VHT20_UNII 2C





ANT2_802.11ac_VHT20_UNII 3






Report No.:
CTK-2021-00840
Page (107) / (250) Pages






ANT3 802.11ac VHT20 UNII 1






ANT3 802.11ac VHT20 UNII 2A






ANT3_802.11ac_VHT20_UNII 2C






ANT3_802.11ac_VHT20_UNII 3






ANT4_802.11ac_VHT20_UNII 1





ANT4_802.11ac_VHT20_UNII 2A





ANT4_802.11ac_VHT20_UNII 2C






ANT4_802.11ac_VHT20_UNII 3



ANT1_802.11n_HT40_UNII_1



ANT1_802.11n_HT40_UNII_2A





ANT1_802.11n_HT40_UNII_2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (112) / (250) Pages






ANT1_802.11n_HT40_UNII 3





ANT2_802.11n_HT40_UNII_1





ANT2_802.11n_HT40_UNII_2A





ANT2_802.11n_HT40_UNII_2C






ANT2_802.11n_HT40_UNII 3





ANT3_802.11n_HT40_UNII_1





ANT3_802.11n_HT40_UNII_2A





ANT3_802.11n_HT40_UNII_2C






ANT3_802.11n_HT40_UNII 3





ANT4_802.11n_HT40_UNII_1





ANT4_802.11n_HT40_UNII_2A





ANT4_802.11n_HT40_UNII_2C






ANT4_802.11n_HT40_UNII 3



ANT1_802.11ac_VHT40_UNII 1



ANT1_802.11ac_VHT40_UNII 2A





ANT1_802.11ac_VHT40_UNII 2C




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (120) / (250) Pages





ANT1_802.11ac_VHT40_UNII 3





ANT2_802.11ac_VHT40_UNI1 1



ANT2_802.11ac_VHT40_UNI1 2A





ANT2_802.11ac_VHT40_UNI1 2C







CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (122) / (250) Pages






ANT2_802.11ac_VHT40_UNII 3



ANT3_802.11ac_VHT40_UNII 1



ANT3_802.11ac_VHT40_UNII 2A





ANT3_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2021-00840
Page (124) / (250) Pages






ANT3_802.11ac_VHT40_UNII 3



ANT4_802.11ac_VHT40_UNII 1



ANT4_802.11ac_VHT40_UNII 2A



ANT4_802.11ac_VHT40_UNII 2C