



10MHz_Low_QPSK_1@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:43:27

10MHz_Low_QPSK_50@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:42:34

10MHz_High_QPSK_1@49



ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:45:27

10MHz_High_QPSK_50@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:44:34


FCC Part 24E

B2 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_High_QPSK_1@5




1.4MHz_High_QPSK_6@0




3MHz_Low_QPSK_1@0




3MHz_Low_QPSK_15@0




3MHz_High_QPSK_1@14




3MHz_High_QPSK_15@0




5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_High_QPSK_1@24



5MHz_High_QPSK_25@0




10MHz_Low_QPSK_1@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:07:38

10MHz_Low_QPSK_50@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:07:25

10MHz_High_QPSK_1@49




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:08:17

10MHz_High_QPSK_50@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:08:05

15MHz_Low_QPSK_1@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:10:38

15MHz_Low_QPSK_75@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:10:25

15MHz_High_QPSK_1@74




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:11:17

15MHz_High_QPSK_75@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:11:04

20MHz_Low_QPSK_1@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:13:00

20MHz_Low_QPSK_100@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:12:46

20MHz_High_QPSK_1@99



ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:13:39

20MHz_High_QPSK_100@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:13:26


FCC Part 27

B4, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_High_QPSK_1@5




1.4MHz_High_QPSK_6@0




3MHz_Low_QPSK_1@0



3MHz_Low_QPSK_15@0




3MHz_High_QPSK_1@14




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:17:00

3MHz_High_QPSK_15@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:16:48

5MHz_Low_QPSK_1@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:18:27

5MHz_Low_QPSK_25@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:18:16

5MHz_High_QPSK_1@24




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:19:05

5MHz_High_QPSK_25@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:18:53

10MHz_Low_QPSK_1@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:20:26

10MHz_Low_QPSK_50@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:20:14

10MHz_High_QPSK_1@49




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:21:04

10MHz_High_QPSK_50@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:20:52

15MHz_Low_QPSK_1@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:22:30

15MHz_Low_QPSK_75@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:22:18

15MHz_High_QPSK_1@74




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:23:09

15MHz_High_QPSK_75@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:22:56

20MHz_Low_QPSK_1@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:24:19

20MHz_Low_QPSK_100@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:24:07

20MHz_High_QPSK_1@99



ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:24:58


20MHz_High_QPSK_100@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:24:45

B7, Normal


5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_High_QPSK_1@24




5MHz_High_QPSK_25@0




10MHz_Low_QPSK_1@0



10MHz_Low_QPSK_50@0




10MHz_High_QPSK_1@49




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:49:28

10MHz_High_QPSK_50@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:49:14

15MHz_Low_QPSK_1@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:50:59

15MHz_Low_QPSK_75@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:50:46

15MHz_High_QPSK_1@74




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:51:45

15MHz_High_QPSK_75@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 22:51:32

20MHz_Low_QPSK_1@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:53:15

20MHz_Low_QPSK_100@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:53:02

20MHz_High_QPSK_1@99



ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:54:03

20MHz_High_QPSK_100@0




ProjectNo.:2402T76961E-RF Tester:Karl Liang
 Date: 30.MAY.2024 22:53:49

Spurious Emissions at Antenna Terminal

FCC Part 22H


B5, Normal

1.4MHz_Low_QPSK_1@0 -24.80dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:31:37

1.4MHz_Low_QPSK_6@0 -26.15dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:31:55

1.4MHz_Middle_QPSK_1@0 -26.12dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:32:14

1.4MHz_Middle_QPSK_6@0 -25.14dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:32:12

1.4MHz_High_QPSK_1@0 -25.13dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:32:51

1.4MHz_High_QPSK_6@0 -25.84dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:33:10

3MHz_Low_QPSK_1@0 -25.02dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:34:29

3MHz_Low_QPSK_15@0 -25.77dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:34:48

3MHz_Middle_QPSK_1@0 -25.91dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:35:08

3MHz_Middle_QPSK_15@0 -26.16dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:35:28

3MHz_High_QPSK_1@0 -25.03dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:35:48

3MHz_High_QPSK_15@0 -24.61dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:36:09

5MHz_Low_QPSK_1@0 -25.77dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:37:30

5MHz_Low_QPSK_25@0 -25.70dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:37:50

5MHz_Middle_QPSK_1@0 -24.97dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:38:11

5MHz_Middle_QPSK_25@0 -25.86dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:38:31

5MHz_High_QPSK_1@0 -25.27dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:38:52

5MHz_High_QPSK_25@0 -25.37dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:39:12

10MHz_Low_QPSK_1@0 -25.21dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:40:58

10MHz_Low_QPSK_50@0 -24.45dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:41:18

10MHz_Middle_QPSK_1@0 -25.15dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:41:40

10MHz_Middle_QPSK_50@0 -25.46dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:42:00

10MHz_High_QPSK_1@0 -25.59dBm



ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:42:22

10MHz_High_QPSK_50@0 -25.28dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:42:42

FCC Part 24E


B2 , Normal

1.4MHz_Low_QPSK_1@0 -24.46dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:47:45

1.4MHz_Low_QPSK_6@0 -24.34dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:48:07

1.4MHz_Middle_QPSK_1@0 -24.19dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:48:30

1.4MHz_Middle_QPSK_6@0 -24.52dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:48:52

1.4MHz_High_QPSK_1@0 -24.54dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:49:14

1.4MHz_High_QPSK_6@0 -24.51dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:49:36

3MHz_Low_QPSK_1@0 -24.22dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:51:33

3MHz_Low_QPSK_15@0 -24.50dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:51:54

3MHz_Middle_QPSK_1@0 -24.66dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:52:16

3MHz_Middle_QPSK_15@0 -24.66dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:52:38

3MHz_High_QPSK_1@0 -24.21dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:53:00

3MHz_High_QPSK_15@0 -23.62dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:53:22

5MHz_Low_QPSK_1@0 -25.08dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:54:34

5MHz_Low_QPSK_25@0 -24.60dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:54:55

5MHz_Middle_QPSK_1@0 -25.02dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:55:17

5MHz_Middle_QPSK_25@0 -23.81dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:55:38

5MHz_High_QPSK_1@0 -24.38dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:56:00

5MHz_High_QPSK_25@0 -24.73dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:56:21

10MHz_Low_QPSK_1@0 -23.20dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:58:24

10MHz_Low_QPSK_50@0 -24.58dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:58:45

10MHz_Middle_QPSK_1@0 -24.87dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:59:08

10MHz_Middle_QPSK_50@0 -24.48dBm




ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:59:30

10MHz_High_QPSK_1@0 -24.10dBm



ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 20:59:53

10MHz_High_QPSK_50@0 -24.65dBm



ProjectNo.:2402T76961E-RF Tester:Karl Liang
Date: 30.MAY.2024 21:00:14