



5MHz\_High\_QPSK\_1@24




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:25:31

5MHz\_High\_QPSK\_25@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:26:21

5MHz\_High\_16QAM\_1@24




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:27:12

5MHz\_High\_16QAM\_25@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:28:02

10MHz\_Low\_QPSK\_1@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:29:47

10MHz\_Low\_QPSK\_50@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:30:34

10MHz\_Low\_16QAM\_1@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:31:22

10MHz\_Low\_16QAM\_50@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:32:09

10MHz\_High\_QPSK\_1@49




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:33:21

10MHz\_High\_QPSK\_50@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:34:16

10MHz\_High\_16QAM\_1@49




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:35:11

10MHz\_High\_16QAM\_50@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:36:05

15MHz\_Low\_QPSK\_1@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:37:40

15MHz\_Low\_QPSK\_75@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:38:28

15MHz\_Low\_16QAM\_1@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:39:17

15MHz\_Low\_16QAM\_75@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:40:06

15MHz\_High\_QPSK\_1@74




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:41:57

15MHz\_High\_QPSK\_75@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:42:55

15MHz\_High\_16QAM\_1@74




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:43:52

15MHz\_High\_16QAM\_75@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:44:50

20MHz\_Low\_QPSK\_1@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:46:37

20MHz\_Low\_QPSK\_100@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:47:28

20MHz\_Low\_16QAM\_1@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:48:18

20MHz\_Low\_16QAM\_100@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:49:08

20MHz\_High\_QPSK\_1@99




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:50:44

20MHz\_High\_QPSK\_100@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:51:44

20MHz\_High\_16QAM\_1@99



ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:52:44

20MHz\_High\_16QAM\_100@0




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 09:53:44

Spurious Emissions at Antenna Terminal

FCC Part 22H


LTE Band 5 , Normal  
 1RB was the worst case

1.4MHz\_Low\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:50:15

1.4MHz\_Middle\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:50:33

1.4MHz\_High\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:50:51

3MHz\_Low\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:51:55

3MHz\_Middle\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:52:13

3MHz\_High\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:52:31

5MHz\_Low\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:53:58

5MHz\_Middle\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:54:15

5MHz\_High\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:54:32

10MHz\_Low\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:55:28

10MHz\_Middle\_QPSK\_1@0(30MHz~9.49GHz)



ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:55:46

10MHz\_High\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:56:04

FCC Part 24E


LTE Band 2 , Normal  
1RB was the worst case

1.4MHz\_Low\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 21.FEB.2025 22:26:24

1.4MHz\_Middle\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:28:51

1.4MHz\_High\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:29:12

3MHz\_Low\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:30:25

3MHz\_Middle\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:30:46

3MHz\_High\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:31:08

5MHz\_Low\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:32:19

5MHz\_Middle\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:32:40

5MHz\_High\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:33:01

10MHz\_Low\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:34:01

10MHz\_Middle\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:34:21

10MHz\_High\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:34:42

15MHz\_Low\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:36:03

15MHz\_Middle\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:36:24

15MHz\_High\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:36:44

20MHz\_Low\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:37:50

20MHz\_Middle\_QPSK\_1@0(30MHz~20.1GHz)



ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:38:09

20MHz\_High\_QPSK\_1@0(30MHz~20.1GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:38:29

FCC Part 27


LTE Band 4 , Normal
1RB was the worst case

1.4MHz\_Low\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:39:39

1.4MHz\_Middle\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:39:58

1.4MHz\_High\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:40:18

3MHz\_Low\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:41:25

3MHz\_Middle\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:41:44

3MHz\_High\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:42:04

5MHz\_Low\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:43:11

5MHz\_Middle\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:43:31

5MHz\_High\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:43:53

10MHz\_Low\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:45:00

10MHz\_Middle\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:45:21

10MHz\_High\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 18:45:42

15MHz\_Low\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:46:49

15MHz\_Middle\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:47:10

15MHz\_High\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:47:30

20MHz\_Low\_QPSK\_1@0(30MHz~18.55GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:48:27

20MHz\_Middle\_QPSK\_1@0(30MHz~18.55GHz)



ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:48:48


20MHz\_High\_QPSK\_1@0(30MHz~18.55GHz)



ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 18:49:10


LTE Band 7 , Normal  
1RB was the worst case

5MHz\_Low\_QPSK\_1@0(30MHz~26.7GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 16:57:18

5MHz\_Middle\_QPSK\_1@0(30MHz~26.7GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 16:57:41

5MHz\_High\_QPSK\_1@0(30MHz~26.7GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 16:58:04

10MHz\_Low\_QPSK\_1@0(30MHz~26.7GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 16:59:06

10MHz\_Middle\_QPSK\_1@0(30MHz~26.7GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 16:59:29

10MHz\_High\_QPSK\_1@0(30MHz~26.7GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
Date: 20.FEB.2025 16:59:51

15MHz\_Low\_QPSK\_1@0(30MHz~26.7GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:01:01

15MHz\_Middle\_QPSK\_1@0(30MHz~26.7GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:01:23

15MHz\_High\_QPSK\_1@0(30MHz~26.7GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:01:46

20MHz\_Low\_QPSK\_1@0(30MHz~26.7GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:02:59

20MHz\_Middle\_QPSK\_1@0(30MHz~26.7GHz)



ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:03:21


20MHz\_High\_QPSK\_1@0(30MHz~26.7GHz)



ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:03:44


LTE Band 38 , Normal  
 1RB was the worst case

5MHz\_Low\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q44141E-RF Teeter:Loge Long  
 Date: 20.FEB.2025 19:04:30

5MHz\_Middle\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q44141E-RF Teeter:Loge Long  
 Date: 20.FEB.2025 19:04:54

5MHz\_High\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q44141E-RF Teeter:Loge Long  
 Date: 20.FEB.2025 19:05:17

10MHz\_Low\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q44141E-RF Teeter:Loge Long  
 Date: 20.FEB.2025 19:06:09

10MHz\_Middle\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q44141E-RF Teeter:Loge Long  
 Date: 20.FEB.2025 19:06:33

10MHz\_High\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q44141E-RF Teeter:Loge Long  
 Date: 20.FEB.2025 19:06:56

15MHz\_Low\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:08:04

15MHz\_Middle\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:08:28

15MHz\_High\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:08:51

20MHz\_Low\_QPSK\_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:10:01

20MHz\_Middle\_QPSK\_1@0(30MHz~27.2GHz)



ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:10:25

20MHz\_High\_QPSK\_1@0(30MHz~27.2GHz)



ProjectNo.:2502Q44141E-RF Tester:Loge Long  
 Date: 20.FEB.2025 19:10:49

\*\*\*\*\* END \*\*\*\*\*