



fourier

Date:06.09.2009

attn: Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern:

The layout, enclosure, RF output power, antenna gain and all other RF parameters and circuitry are identical in the DNL804, DNL808, and DNL810 units.

Please contact me if there is any information you may need.

Sincerely,

Haim Bila

QA Manager
Fourier Systems Ltd.

Fourier Systems Ltd.
7435 Oakland Mills Road
Columbia, MD 21046
Tel: 410-326-7899