

**From:** Daphne.Liang@ccsrf.com  
**To:** Alan Lane <Alan.Lane@phoenix-testlab.de>  
**cc:** steven.chunag@ccsrf.com

---

**Date:** Thursday, March 04, 2010 02:00PM  
**Subject:** 回信: FCC ID: XLG-FS-GM201 (90522301)

Dear Alan:

For the antenna information,after checked with our client, they confirmed will apply for "Limited module" for using standard antenna type and with professionally installed.

Please also find the updated user manual(990304)REV for address it on page 20.Thank you.



**BEST REGARDS**

**Daphne Liang 梁鈺如**

Compliance Certification Services Inc. (Tainan Lab)  
No.8, Jiu Cheng Ling, Jiaokeng Village, Sinhua Township,  
Tainan Hsien 712, Taiwan R.O.C.  
Tel: 886-6-5802201 ext:201  
Fax: 886-6-5802202  
E-mail: [Daphne.liang@ccsrf.com](mailto:Daphne.liang@ccsrf.com)  
Website: [www.ccsrf.com](http://www.ccsrf.com)

寄件人:	Alan Lane <Alan.Lane@phoenix-testlab.de>
收件人:	daphne.liang@ccsrf.com
副本抄送:	steven.chunag@ccsrf.com
日期:	2010/03/04 下午 01:41
主旨:	FCC ID: XLG-FS-GM201 (90522301)

---

Dear Daphne,

From the antenna relevant information, the standard antenna type is used for this device and does not comply with FCC 15.203 requirement for antenna part.  
please address it.

Thank you.

Regards,  
Alan Lane

-----  
PHOENIX TESTLAB GmbH  
Alan Lane  
FCC TCB, IC FCB  
Koenigswinkel 10  
32825 Blomberg  
Germany

reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission. Thank you for your attention.

Attachments:

FS-GM201\_User's Manual(990304)REV.pdf