

Andrew Wireless Systems GmbH
Industriering 10
86675 Buchdorf
Germany





















Nemko Canada Inc
303 River Road
Ottawa
K1V 1H2
Canada

ATTN.: Reviewing Engineer

FCC ID: XS5-UAP27171937

Model differences - Annex

Photographic comparison to show the hardware differences among the variants under this filing:

| Views | UAP 2 7E/17E/19/37T C-PE | UAP 2 7E/17E/19/37T F-DC | UAP 2 17E/19 C-PE | UAP 2 17E/19 F-DC |
|-------------------------|--|--|--|--|
| Antennas side |  |  |  |  |
| Radio Modules installed |  |  |  |  |
| Base Band Card (all) |  |  |  |  |
| Data & Power Entry |   |   |   |   |

Signed: 

Printed name: Jiri Cecka
Title: Quality Manager
Date: 10/9/2023