


Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


A.4.2 Measurement Plots

- CDD Mode




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303


- SDM Mode




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303








Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

A.5 EMISSION LIMITATIONS MEASUREMENT

Test Date	2018/03/23	Temp./Hum.	25°C/54%
Mode	802.11a	UNII Band	I
		Frequency	TX 5180MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		6.02	







Test Date	2018/03/23	Temp./Hum.	25°C/54%
Mode	802.11a	UNII Band	I
Cable Loss	1.74dB	Frequency	TX 5200MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
			6.02







Test Date	2018/03/23	Temp./Hum.	25°C/54%
Mode	802.11a	UNII Band	I
Cable Loss	1.74dB	Frequency	TX 5240MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
			6.02





Test Date	2018/03/23	Temp./Hum.	25°C/54%
Mode	802.11a	UNII Band	II-2A
Cable Loss	1.74dB	Frequency	TX 5260MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
			6.02







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/03/23	Temp./Hum.	25°C/54%
Mode	802.11a	UNII Band	II-2A
		Frequency	TX 5300MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		6.02	





Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/03/23	Temp./Hum.	25°C/54%
Mode	802.11a	UNII Band	II-2A
		Frequency	TX 5320MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		6.02	




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Test Date	2018/03/23	Temp./Hum.	25℃/54%
Mode	802.11a	UNII Band	II-2C
		Frequency	TX 5500MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		6.02	



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

