

	Report No: R3112 Issue No: 1	FCC ID: XX6-SRG3500XB	
Test No: T4354		Test Photos	Page: 1 of 4



dB Technology

..... (Cambridge Ltd.)

EMC
Testing

EMC
Consultancy

EMC
Training

23, Headington Drive,
Cambridge.
CB1 9HE
Tel : 01954 251974 (test site)
or : 01223 241140 (accounts)
Fax : 01954 251907
web : www.dbtechnology.co.uk
email: mail@dbtechnology.co.uk

Test Photos

**Performed at:
TWENTY PENCE TEST SITE**

**Twenty Pence Road,
Cottenham,
Cambridge
U.K.
CB24 8PS**

on

Sepura PLC

SRG3500

dated

22nd June 2012


Document History

Issue	Date	Affected page(s)	Description of modifications	Revised by	Approved by
1	06/07/12		Initial release		

Based on report template:
v090319

*This report shall not be reproduced except in full, without the written approval of:
dB Technology (Cambridge) Ltd.*

	Report No: R3112 Issue No: 1	FCC ID: XX6-SRG3500XB	
Test No: T4354		Test Photos	Page: 2 of 4




Photograph 1 SRG3500: Connected to Agilent Analyser

	Report No: R3112 Issue No: 1	FCC ID: XX6-SRG3500XB	
Test No: T4354		Test Photos	Page: 3 of 4




Photograph 2 Configuration 1: Radiated Emissions - Front




Photograph 3 Configuration 1: Radiated Emissions - Back

	Report No: R3112 Issue No: 1	FCC ID: XX6-SRG3500XB	
Test No: T4354		Test Photos	Page: 4 of 4



Photograph 4 DMU: Radiated Emissions - Front



Photograph 5 DMU: Radiated Emissions - Back