


C8,C9 need Approaches the 13 Pin



NOTE 3:  
If don't consider ESD, The R11  
should be removed, otherwise all of  
them should be added.

