



Date: 9.MAY.2024 10:45:31




Date: 9.MAY.2024 10:45:41

Band5\_5MHz\_QPSK\_20525\_1RB#0\_3000~1000  
0\_3000~10000

Band5\_5MHz\_16QAM\_20525\_1RB#0\_0.009~0.15  
\_0.009~0.15




Date: 9.MAY.2024 10:45:49




Date: 9.MAY.2024 10:45:58

Band5\_5MHz\_16QAM\_20525\_1RB#0\_0.15~30  
0.15~30


Band5\_5MHz\_16QAM\_20525\_1RB#0\_30~1000\_3  
0~1000





Date: 9.MAY.2024 10:46:06





Date: 9.MAY.2024 10:46:15







Band5\_5MHz\_QPSK\_20625\_1RB#0\_3000~1000  
 0\_3000~10000


Band5\_5MHz\_16QAM\_20625\_1RB#0\_0.009~0.15  
 0\_009~0.15




Band5\_5MHz\_16QAM\_20625\_1RB#0\_0.15~30  
 0.15~30


Band5\_5MHz\_16QAM\_20625\_1RB#0\_30~1000\_3  
 0~1000








Date: 9.MAY.2024 11:16:14




Date: 9.MAY.2024 11:16:23

Band5\_10MHz\_QPSK\_20450\_1RB#0\_3000~10000

Band5\_10MHz\_16QAM\_20450\_1RB#0\_0.009~0.15




Date: 9.MAY.2024 11:16:32




Date: 9.MAY.2024 11:16:41

Band5\_10MHz\_16QAM\_20450\_1RB#0\_0.15~30

Band5\_10MHz\_16QAM\_20450\_1RB#0\_30~1000



Date: 9.MAY.2024 11:16:49



Date: 9.MAY.2024 11:16:58