



Date: 9.MAY.2024 18:51:05




Date: 9.MAY.2024 18:51:14

Band25_1.4MHz_QPSK_26365_1RB#0_3000~2000_3000~20000

Band25_1.4MHz_16QAM_26365_1RB#0_0.009~0.15_0.009~0.15




Date: 9.MAY.2024 18:51:23




Date: 9.MAY.2024 18:51:31

Band25_1.4MHz_16QAM_26365_1RB#0_0.15~3_0_0.15~30


Band25_1.4MHz_16QAM_26365_1RB#0_30~100_0_30~1000





Date: 9.MAY.2024 18:51:40




Date: 9.MAY.2024 18:51:49











Date: 9.MAY.2024 19:21:35




Date: 9.MAY.2024 19:21:44

Band25_3MHz_QPSK_26055_1RB#0_3000~20000

Band25_3MHz_16QAM_26055_1RB#0_0.009~0.15




Date: 9.MAY.2024 19:21:53




Date: 9.MAY.2024 19:22:01

Band25_3MHz_16QAM_26055_1RB#0_0.15~30

Band25_3MHz_16QAM_26055_1RB#0_30~1000



Date: 9.MAY.2024 19:22:10



Date: 9.MAY.2024 19:22:19