



Date: 10.MAY.2024 18:49:21




Date: 10.MAY.2024 18:49:57

Band38_15MHz_QPSK_37825_1RB#0_20000~27000

Band38_15MHz_16QAM_37825_1RB#0_0.009~0.15




Date: 10.MAY.2024 18:50:17




Date: 10.MAY.2024 18:50:38

Band38_15MHz_16QAM_37825_1RB#0_0.15~30


Band38_15MHz_16QAM_37825_1RB#0_30~1000




Date: 10.MAY.2024 18:50:59




Date: 10.MAY.2024 18:51:23






Date: 10.MAY.2024 18:53:25




Date: 10.MAY.2024 18:54:01

Band38_15MHz_QPSK_38000_1RB#0_20000~27000

Band38_15MHz_16QAM_38000_1RB#0_0.009~0.15




Date: 10.MAY.2024 18:54:21




Date: 10.MAY.2024 18:54:42

Band38_15MHz_16QAM_38000_1RB#0_0.15~30

Band38_15MHz_16QAM_38000_1RB#0_30~1000



Date: 10.MAY.2024 18:55:03



Date: 10.MAY.2024 18:55:27

