



NVNT	ax80	5290	Ant1	-13.72	0	-13.72	11	Pass
NVNT	ax80	5530	Ant1	-13.91	0	-13.91	11	Pass
NVNT	ax80	5610	Ant1	-13.97	0	-13.97	11	Pass
NVNT	ax80	5210	Ant2	-17.04	0	-17.04	11	Pass
NVNT	ax80	5290	Ant2	-16.67	0	-16.67	11	Pass
NVNT	ax80	5530	Ant2	-15.56	0	-15.56	11	Pass
NVNT	ax80	5610	Ant2	-16.44	0	-16.44	11	Pass
NVNT	ax80	5210	Ant1	-19.81	0	-19.81	11	Pass
NVNT	ax80	5210	Ant2	-21.71	0	-21.71	11	Pass
NVNT	ax80	5210	Sum	-17.65	0	-17.65	9.32	Pass
NVNT	ax80	5290	Ant1	-17.82	0	-17.82	11	Pass
NVNT	ax80	5290	Ant2	-20.61	0	-20.61	11	Pass
NVNT	ax80	5290	Sum	-15.98	0	-15.98	9.32	Pass
NVNT	ax80	5530	Ant1	-17.7	0	-17.7	11	Pass
NVNT	ax80	5530	Ant2	-20.17	0	-20.17	11	Pass
NVNT	ax80	5530	Sum	-15.75	0	-15.75	9.32	Pass
NVNT	ax80	5610	Ant1	-18.57	0	-18.57	11	Pass
NVNT	ax80	5610	Ant2	-21.33	0	-21.33	11	Pass
NVNT	ax80	5610	Sum	-16.72	0	-16.72	9.32	Pass
Condition	Mode	Frequency (MHz)	Antenna	Conducted PSD (dBm/500kHz)	Duty Factor (dB)	Total PSD (dBm/500kHz)	Limit (dBm/500kHz)	Verdict
NVNT	a	5745	Ant1	-5.04	0	-5.04	30	Pass
NVNT	a	5785	Ant1	-4.55	0	-4.55	30	Pass
NVNT	a	5825	Ant1	-5.37	0	-5.37	30	Pass
NVNT	a	5745	Ant2	-7.45	0	-7.45	30	Pass
NVNT	a	5785	Ant2	-7.91	0	-7.91	30	Pass
NVNT	a	5825	Ant2	-8.68	0	-8.68	30	Pass
NVNT	n20	5745	Ant1	-6.8	0	-6.8	30	Pass
NVNT	n20	5785	Ant1	-7.11	0	-7.11	30	Pass
NVNT	n20	5825	Ant1	-7.53	0	-7.53	30	Pass
NVNT	n20	5745	Ant2	-13.5	0	-13.5	30	Pass
NVNT	n20	5785	Ant2	-13.73	0	-13.73	30	Pass
NVNT	n20	5825	Ant2	-13.83	0	-13.83	30	Pass
NVNT	n20	5745	Ant1	-10.61	0	-10.61	30	Pass
NVNT	n20	5745	Ant2	-14.63	0	-14.63	30	Pass
NVNT	n20	5745	Sum	-9.16	0	-9.16	28.32	Pass
NVNT	n20	5785	Ant1	-10.36	0	-10.36	30	Pass
NVNT	n20	5785	Ant2	-14.99	0	-14.99	30	Pass
NVNT	n20	5785	Sum	-9.07	0	-9.07	28.32	Pass
NVNT	n20	5825	Ant1	-10.44	0	-10.44	30	Pass
NVNT	n20	5825	Ant2	-15.2	0	-15.2	30	Pass
NVNT	n20	5825	Sum	-9.19	0	-9.19	28.32	Pass
NVNT	n40	5755	Ant1	-9.23	0	-9.23	30	Pass
NVNT	n40	5795	Ant1	-8.77	0	-8.77	30	Pass
NVNT	n40	5755	Ant2	-15.86	0	-15.86	30	Pass
NVNT	n40	5795	Ant2	-16.1	0	-16.1	30	Pass
NVNT	n40	5755	Ant1	-13.29	0	-13.29	30	Pass
NVNT	n40	5755	Ant2	-17.41	0	-17.41	30	Pass
NVNT	n40	5755	Sum	-11.87	0	-11.87	28.32	Pass
NVNT	n40	5795	Ant1	-12.54	0	-12.54	30	Pass
NVNT	n40	5795	Ant2	-17.51	0	-17.51	30	Pass
NVNT	n40	5795	Sum	-11.34	0	-11.34	28.32	Pass
NVNT	ac20	5745	Ant1	-10.08	0	-10.08	30	Pass
NVNT	ac20	5785	Ant1	-9.66	0	-9.66	30	Pass
NVNT	ac20	5825	Ant1	-10.43	0	-10.43	30	Pass
NVNT	ac20	5745	Ant2	-13.88	0	-13.88	30	Pass
NVNT	ac20	5785	Ant2	-17.07	0	-17.07	30	Pass
NVNT	ac20	5825	Ant2	-14.88	0	-14.88	30	Pass
NVNT	ac20	5745	Ant1	-16.23	0	-16.23	30	Pass
NVNT	ac20	5745	Ant2	-19.31	0	-19.31	30	Pass
NVNT	ac20	5745	Sum	-14.49	0	-14.49	28.32	Pass
NVNT	ac20	5785	Ant1	-15.18	0	-15.18	30	Pass
NVNT	ac20	5785	Ant2	-19.95	0	-19.95	30	Pass
NVNT	ac20	5785	Sum	-13.93	0	-13.93	28.32	Pass
NVNT	ac20	5825	Ant1	-15.09	0	-15.09	30	Pass
NVNT	ac20	5825	Ant2	-20.23	0	-20.23	30	Pass
NVNT	ac20	5825	Sum	-13.93	0	-13.93	28.32	Pass
NVNT	ac40	5755	Ant1	-16.16	0	-16.16	30	Pass
NVNT	ac40	5795	Ant1	-16.06	0	-16.06	30	Pass
NVNT	ac40	5755	Ant2	-16.97	0	-16.97	30	Pass
NVNT	ac40	5795	Ant2	-17.06	0	-17.06	30	Pass
NVNT	ac40	5755	Ant1	-17.76	0	-17.76	30	Pass
NVNT	ac40	5755	Ant2	-21.94	0	-21.94	30	Pass
NVNT	ac40	5755	Sum	-16.36	0	-16.36	28.32	Pass
NVNT	ac40	5795	Ant1	-17.55	0	-17.55	30	Pass
NVNT	ac40	5795	Ant2	-22.56	0	-22.56	30	Pass
NVNT	ac40	5795	Sum	-16.36	0	-16.36	28.32	Pass
NVNT	ac80	5775	Ant1	-16.35	0	-16.35	30	Pass
NVNT	ac80	5775	Ant2	-20.07	0	-20.07	30	Pass
NVNT	ac80	5775	Ant1	-22.37	0	-22.37	30	Pass
NVNT	ac80	5775	Ant2	-26.54	0	-26.54	30	Pass
NVNT	ac80	5775	Sum	-20.96	0	-20.96	28.32	Pass
NVNT	ax20	5745	Ant1	-10.66	0	-10.66	30	Pass
NVNT	ax20	5785	Ant1	-10.73	0	-10.73	30	Pass
NVNT	ax20	5825	Ant1	-10.56	0	-10.56	30	Pass
NVNT	ax20	5745	Ant2	-14.83	0	-14.83	30	Pass
NVNT	ax20	5785	Ant2	-15.15	0	-15.15	30	Pass
NVNT	ax20	5825	Ant2	-15.02	0	-15.02	30	Pass
NVNT	ax20	5745	Ant1	-16.69	0	-16.69	30	Pass
NVNT	ax20	5745	Ant2	-19.65	0	-19.65	30	Pass
NVNT	ax20	5745	Sum	-14.91	0	-14.91	28.32	Pass
NVNT	ax20	5785	Ant1	-16.25	0	-16.25	30	Pass
NVNT	ax20	5785	Ant2	-20.4	0	-20.4	30	Pass
NVNT	ax20	5785	Sum	-14.84	0	-14.84	28.32	Pass



NVNT	ax20	5825	Ant1	-15.21	0	-15.21	30	Pass
NVNT	ax20	5825	Ant2	-19.85	0	-19.85	30	Pass
NVNT	ax20	5825	Sum	-13.93	0	-13.93	28.32	Pass
NVNT	ax40	5755	Ant1	-12.3	0	-12.3	30	Pass
NVNT	ax40	5795	Ant1	-12.31	0	-12.31	30	Pass
NVNT	ax40	5755	Ant2	-17.12	0	-17.12	30	Pass
NVNT	ax40	5795	Ant2	-17.76	0	-17.76	30	Pass
NVNT	ax40	5755	Ant1	-18.71	0	-18.71	30	Pass
NVNT	ax40	5755	Ant2	-22.07	0	-22.07	30	Pass
NVNT	ax40	5755	Sum	-17.06	0	-17.06	28.32	Pass
NVNT	ax40	5795	Ant1	-18.01	0	-18.01	30	Pass
NVNT	ax40	5795	Ant2	-22.89	0	-22.89	30	Pass
NVNT	ax40	5795	Sum	-16.79	0	-16.79	28.32	Pass
NVNT	ax80	5775	Ant1	-16.15	0	-16.15	30	Pass
NVNT	ax80	5775	Ant2	-20.09	0	-20.09	30	Pass
NVNT	ax80	5775	Ant1	-22.14	0	-22.14	30	Pass
NVNT	ax80	5775	Ant2	-26.42	0	-26.42	30	Pass
NVNT	ax80	5775	Sum	-20.76	0	-20.76	28.32	Pass



































































































































































