


Out of band emission,Band Edge

FCC Part 22H


B5 , Normal

1.4MHz_Low_QPSK_1@0 -20.92dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:11:57

1.4MHz_Low_QPSK_6@0 -24.59dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:11:27

1.4MHz_Low_16QAM_1@0 -22.23dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:57:40

1.4MHz_Low_16QAM_6@0 -25.89dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:57:10

1.4MHz_High_QPSK_1@5 -17.45dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:13:07

1.4MHz_High_QPSK_6@0 -25.90dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:12:37

1.4MHz_High_16QAM_1@5 -22.01dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:58:50

1.4MHz_High_16QAM_6@0 -27.94dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:58:20

3MHz_Low_QPSK_1@0 -18.59dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:14:53

3MHz_Low_QPSK_15@0 -26.68dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:14:20

3MHz_Low_16QAM_1@0 -19.15dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:00:33

3MHz_Low_16QAM_15@0 -26.51dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:00:00

3MHz_High_QPSK_1@14 -20.45dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:16:09

3MHz_High_QPSK_15@0 -25.08dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:15:36

3MHz_High_16QAM_1@14 -19.27dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:01:50

3MHz_High_16QAM_15@0 -27.19dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:01:16

5MHz_Low_QPSK_1@0 -16.78dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:18:06

5MHz_Low_QPSK_25@0 -24.44dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:17:28

5MHz_Low_16QAM_1@0 -18.31dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:04:07

5MHz_Low_16QAM_25@0 -26.21dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:03:29

5MHz_High_QPSK_1@24 -18.12dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:19:32

5MHz_High_QPSK_25@0 -24.79dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:18:54

5MHz_High_16QAM_1@24 -18.93dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:05:32

5MHz_High_16QAM_25@0 -27.39dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:04:54

10MHz_Low_QPSK_1@0 -31.29dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:21:48

10MHz_Low_QPSK_50@0 -30.32dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:20:59

10MHz_Low_16QAM_1@0 -31.70dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:07:46

10MHz_Low_16QAM_50@0 -33.42dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:06:58

10MHz_High_QPSK_1@49 -32.56dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:23:36

10MHz_High_QPSK_50@0 -31.50dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:22:47

10MHz_High_16QAM_1@49 -32.32dBm



ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:09:34

10MHz_High_16QAM_50@0 -32.95dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:08:45

FCC Part 24E


B2 , Normal

1.4MHz_Low_QPSK_1@0 -18.45dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:32:43

1.4MHz_Low_QPSK_6@0 -21.60dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:32:34

1.4MHz_Low_16QAM_1@0 -19.61dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:40:31

1.4MHz_Low_16QAM_6@0 -23.76dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:40:23

1.4MHz_High_QPSK_1@5 -19.52dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:33:10

1.4MHz_High_QPSK_6@0 -23.43dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:33:01

1.4MHz_High_16QAM_1@5 -20.67dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 09:40:56

1.4MHz_High_16QAM_6@0 -22.67dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 09:40:48

3MHz_Low_QPSK_1@0 -17.43dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 15:34:06

3MHz_Low_QPSK_15@0 -20.12dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 15:33:58

3MHz_Low_16QAM_1@0 -18.72dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 09:41:47

3MHz_Low_16QAM_15@0 -21.34dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 09:41:39

3MHz_High_QPSK_1@14 -17.35dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:34:33

3MHz_High_QPSK_15@0 -19.86dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:34:24

3MHz_High_16QAM_1@14 -18.54dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:42:12

3MHz_High_16QAM_15@0 -22.07dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:42:04

5MHz_Low_QPSK_1@0 -16.84dBm



ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:35:29

5MHz_Low_QPSK_25@0 -21.08dBm



ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:35:21