



10MHz_Low_QPSK_1@0 -30.91dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:45:18

10MHz_Low_QPSK_50@0 -27.53dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:45:09

10MHz_Low_16QAM_1@0 -33.53dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:52:03

10MHz_Low_16QAM_50@0 -27.28dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:51:55

10MHz_High_QPSK_1@49 -33.01dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:45:46

10MHz_High_QPSK_50@0 -30.06dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:45:37

10MHz_High_16QAM_1@49 -33.30dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:52:29

10MHz_High_16QAM_50@0 -28.80dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:52:20

15MHz_Low_QPSK_1@0 -22.66dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:46:47

15MHz_Low_QPSK_75@0 -27.35dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:46:38

15MHz_Low_16QAM_1@0 -24.79dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:53:23

15MHz_Low_16QAM_75@0 -27.55dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:53:15

15MHz_High_QPSK_1@74 -24.31dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 15:47:16

15MHz_High_QPSK_75@0 -30.39dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 15:47:07

15MHz_High_16QAM_1@74 -24.75dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 09:53:50

15MHz_High_16QAM_75@0 -29.75dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 09:53:41

20MHz_Low_QPSK_1@0 -28.78dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 15:48:18

20MHz_Low_QPSK_100@0 -29.16dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 15:48:08

20MHz_Low_16QAM_1@0 -30.23dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:54:46

20MHz_Low_16QAM_100@0 -29.24dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:54:36

20MHz_High_QPSK_1@99 -30.18dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:48:47

20MHz_High_QPSK_100@0 -33.19dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 15:48:38

20MHz_High_16QAM_1@99 -31.85dBm



ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:55:13


20MHz_High_16QAM_100@0 -31.66dBm



ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 09:55:04


B7 , Normal

5MHz_Low_QPSK_1@0 -24.43dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:23:35

5MHz_Low_QPSK_25@0 -22.98dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:23:25

5MHz_Low_16QAM_1@0 -23.07dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:12:07

5MHz_Low_16QAM_25@0 -23.72dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:11:58

5MHz_High_QPSK_1@24 -23.63dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:24:11

5MHz_High_QPSK_25@0 -21.57dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:24:01

5MHz_High_16QAM_1@24 -24.93dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 2.JUL.2024 10:12:43

5MHz_High_16QAM_25@0 -22.83dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 2.JUL.2024 10:12:33

10MHz_Low_QPSK_1@0 -25.96dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 21.JUN.2024 16:25:19

10MHz_Low_QPSK_50@0 -24.08dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 21.JUN.2024 16:25:09

10MHz_Low_16QAM_1@0 -29.17dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 2.JUL.2024 10:13:41

10MHz_Low_16QAM_50@0 -25.57dBm




ProjectNo.: RKSA240112001 Tester:Jason Lu
 Date: 2.JUL.2024 10:13:32

10MHz_High_QPSK_1@49 -29.28dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:25:56

10MHz_High_QPSK_50@0 -27.82dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:25:46

10MHz_High_16QAM_1@49 -25.81dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:14:17

10MHz_High_16QAM_50@0 -29.48dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:14:08

15MHz_Low_QPSK_1@0 -24.47dBm



ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:27:02

15MHz_Low_QPSK_75@0 -24.75dBm



ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:26:52