

3. Internal Photograph of EUT


Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM





Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Note:

WWAN Main Antenna 1: GSM850<Tx/Rx>; WCDMA: B5<Tx/Rx>; LTE: B5/7/12/13/17/38<Tx/Rx>

WWAN Main Antenna 2: GSM1900<Tx/Rx>; WCDMA: B2/4<Tx/Rx>; LTE: B2/4/66<Tx/Rx>

WWAN Diversity Antenna 1: GSM850<Rx>; WCDMA: B5<Rx>; LTE: B5/7/12/13/17/38<Rx>

WWAN Diversity Antenna 2: GSM1900<Rx>; WCDMA: B2/4<Rx>; LTE: B2/4/66<Rx>

Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;
Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;
Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM






Brand Name: LG;


The photograph displays the disassembled internal parts of a mobile phone against a blue background. On the left, a black ruler provides a scale from 0 to 100 mm. The components are arranged vertically. At the top is a small, dark rectangular component, likely a camera or sensor module. Below it is a larger, complex circuit board featuring various chips, capacitors, and connectors. To the right of this board is a large, silver-colored battery pack with visible internal structure and labels such as "MAIN PCB", "SUB PCB", and "680MM1C7181". A small, circular gold-colored component is also visible near the bottom right. The overall layout suggests a technical inspection or repair process.



Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;**Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM**


Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM






Brand Name: LG;
Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM





Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM





Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM








Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;**Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM**


Brand Name: LG;**Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM**

Brand Name: LG;**Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM**




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM






Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM


Sample 2 (Single SIM Card)



Brand Name: LG;**Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM**

Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;
Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;
Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;**Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM**

Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM





Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM





Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM






Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM






Brand Name: LG;
Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM





Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM






Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;


Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM






Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM




Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM





Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM



Brand Name: LG;

Model Name: LM-K410FMW, LMK410FMW, K410FMW, LM-K410HM, LMK410HM, K410HM

