



5.3. SETUP PHOTOS

RADIATED MEASUREMENT SETUP (BELOW 1 GHz)

RADIATED FRONT PHOTO (BELOW 1 GHz) – USB ADAPTER




RADIATED BACK PHOTO (BELOW 1 GHz) – USB ADAPTER




RADIATED MEASUREMENT SETUP (BELOW 1 GHz)

RADIATED FRONT PHOTO (BELOW 1 GHz) – LAPTOP




RADIATED BACK PHOTO (BELOW 1 GHz) – LAPTOP




RADIATED MEASUREMENT SETUP (ABOVE 1 GHz)



RADIATED FRONT PHOTO (ABOVE 1 GHz) – USB ADAPTER



RADIATED BACK PHOTO (ABOVE 1 GHz) – USB ADAPTER



RADIATED MEASUREMENT SETUP (ABOVE 1 GHz)




POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP

LINE CONDUCTED FRONT PHOTO (PS-USB ADAPTER)



LINE CONDUCTED BACK PHOTO (PS-USB ADAPTER)



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP

LINE CONDUCTED FRONT PHOTO (PS-LAPTOP)



LINE CONDUCTED BACK PHOTO (PS-LAPTOP)



END OF REPORT