

### 3. Internal Photograph of EUT


Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150



Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150







Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150



Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150



Brand Name: LG; Model Name: LG-X150, X150, LGX150




Brand Name: LG; Model Name: LG-X150, X150, LGX150





Brand Name: LG; Model Name: LG-X150, X150, LGX150



Brand Name: LG; Model Name: LG-X150, X150, LGX150



Brand Name: LG; Model Name: LG-X150, X150, LGX150



Brand Name: LG; Model Name: LG-X150, X150, LGX150

