

3. Internal Photograph of EUT

Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g



Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g



Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g




Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g



Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g



Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g



Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g



Brand Name: LG; Model Name: LG-X170g, X170g, LGX170g, LG-X165g, X165g, LGX165g

