

August 29, 2011

Dear Timco Representative,

1. Fixed the model name on all documents from m400 to M400
2. EUT was tested in all 3 orthogonal axis. This text has been added to page 6 of the test report.
3. Additional statement was added in the user manual per RSS Gen .

This covers the 3 problem on hold emails issued per –

REFERENCE: JOB 1964UC11

REFERENCE: JOB 1964UC11 (Continued)

REFERENCE: JOB 1965IC11



---

Ashwani Malhotra

Global EMC Labs Inc

180 Brodie Dr Unit 2

Richmond Hill ON

L4B-3K8