

AMPAK Technology Inc.

3F, No.1, Jen AI Road, Hsinchu Industrial Park, Hsinchu, Taiwan

Attestation Statements

To: Federal Communications Commission

Date: Jul. 8, 25

7435 Oakland Mills Road,

Columbia, MD 21046, USA

Subject: Attestation of Compliance with FCC Covered List Software Requirements

FCC ID: FCC ID: ZQ6-AP5811SA

Product Name: AP5811SA

This letter serves as an attestation that the equipment identified above ☐ is / ☒ is not (select one) "covered" software as defined under the Federal Communications Commission (FCC) Covered List requirements, as outlined in **FCC 22-84** and **KDB 986446**.

Specifically, the undersigned certifies that the equipment for which authorization is sought:

1. **Does not contain** cybersecurity or anti-virus software produced or provided by **Kaspersky Lab, Inc.** or any of its successors, assignees, parents, subsidiaries, affiliates, or any entity that has rebranded or relabeled software produced by the aforementioned entities.
2. **Does not have the capability** to store, run, or deliver any software identified on the FCC Covered List, including but not limited to cybersecurity and anti-virus software.

To support this attestation, the appendix evaluation documentation has been prepared and is included in the certification filing.

This attestation is based on a thorough evaluation of the device's design, functionality, and software environment. The undersigned affirms that the information provided is accurate and complete to the best of their knowledge.

Sincerely yours,



Name/Title :	Changyi Tsai/Manager
Company:	AMPAK Technology Inc.
Address:	3F, No.1, Jen AI Road, Hsinchu Industrial Park, Hsinchu, Taiwan
Phone:	886-3-600-9666
Fax:	886-3-600-3535
E-Mail:	cytsai@gemtek.com.tw

AMPAK Technology Inc.

3F, No.1, Jen Ai Road, Hsinchu Industrial Park, Hsinchu, Taiwan

Evaluation regarding to the Covered List Software:		
Compliance Methodology	Evaluation Process	Results
Device is Inherent compliance	☒ The Chipset(s) used is limited to run the Cybersecurity or anti-virus software.	The RF chip SYN43711 doesn't support the mentioned function.
	☐ The Memory used is limited to run the Cybersecurity or anti-virus software.	
	☐ There is storage capacity limitation for store or install the Cybersecurity or anti-virus software.	
	☐ Operating system used is limited to run, install or deliver the Cybersecurity or anti-virus software.	
Device is not Inherent compliance	☐ Evaluation Based on Software Bill of Materials (SBOM)	
	☐ Evaluation Based on Scan for Software on the device	
	☐ Evaluation Based on Filesystem scan	
	☐ Evaluation Based on Running software check	