

External photographs of equipment under test



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBXIR21 PMN: Spark
Test: 211004
Test to: CFR47 15C, RSS-210, RSS-247
File: FBXIR21 ExtPho

SN's: FCC1 / FCC2
FCC ID: 2A29A-FBXIR21
IC: 27842-FBXIR21
Date: November 18, 2021
Page 1 of 3



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBXIR21 PMN: Spark
Test: 211004
Test to: CFR47 15C, RSS-210, RSS-247
File: FBXIR21 ExtPho

SN's: FCC1 / FCC2
FCC ID: 2A29A-FBXIR21
IC: 27842-FBXIR21
Date: November 18, 2021
Page 2 of 3



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBXIR21 PMN: Spark
Test: 211004
Test to: CFR47 15C, RSS-210, RSS-247
File: FBXIR21 ExtPho

SN's: FCC1 / FCC2
FCC ID: 2A29A-FBXIR21
IC: 27842-FBXIR21
Date: November 18, 2021
Page 3 of 3