



15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:02:40

15MHz_Low_QPSK_75@0(30MHz~27.2GHz)




ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:03:01

15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:03:22

15MHz_Middle_QPSK_75@0(30MHz~27.2GHz)




ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:03:44

15MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:04:06

15MHz_High_QPSK_75@0(30MHz~27.2GHz)




ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:04:28

20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:05:28

20MHz_Low_QPSK_100@0(30MHz~27.2GHz)




ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:05:49

20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:06:10

20MHz_Middle_QPSK_100@0(30MHz~27.2GHz)




ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:06:31

20MHz_High_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:06:52


20MHz_High_QPSK_100@0(30MHz~27.2GHz)



ProjectNo.: RKSA240808001 Tester: Neil Zhou
Date: 20 FEB 2025 18:07:13


B66 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:31:49

1.4MHz_Low_QPSK_6@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:32:04

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:32:20

1.4MHz_Middle_QPSK_6@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:32:35

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:32:51

1.4MHz_High_QPSK_6@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:33:08

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:33:54

3MHz_Low_QPSK_15@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:34:09

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:34:24

3MHz_Middle_QPSK_15@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:34:40

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:34:55

3MHz_High_QPSK_15@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:35:11

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:35:51

5MHz_Low_QPSK_25@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:36:07

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:36:22

5MHz_Middle_QPSK_25@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:36:38

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:36:54

5MHz_High_QPSK_25@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:37:10

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:38:03

10MHz_Low_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:38:18

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:38:34

10MHz_Middle_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:38:49

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:39:05

10MHz_High_QPSK_50@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:39:21

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:40:09

15MHz_Low_QPSK_75@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:40:25

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:40:41

15MHz_Middle_QPSK_75@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:40:57

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:41:13

15MHz_High_QPSK_75@0(30MHz~18.8GHz)




ProjectNo.: RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:41:30

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:42:14

20MHz_Low_QPSK_100@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:42:30

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:42:46

20MHz_Middle_QPSK_100@0(30MHz~18.8GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:43:02

20MHz_High_QPSK_1@0(30MHz~18.8GHz)



ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:43:18


20MHz_High_QPSK_100@0(30MHz~18.8GHz)



ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 21.FEB.2025 17:43:35


B41, Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20 FEB 2025 17:03:33

5MHz_Low_QPSK_25@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20 FEB 2025 17:03:53

5MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20 FEB 2025 17:04:13

5MHz_Middle_QPSK_25@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20 FEB 2025 17:04:33

5MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20 FEB 2025 17:04:53

5MHz_High_QPSK_25@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20 FEB 2025 17:05:13

_10MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:05:35

_10MHz_Low_QPSK_50@0(30MHz~27.55GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:05:55

_10MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:06:15

_10MHz_Middle_QPSK_50@0(30MHz~27.55GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:06:38

_10MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:06:56

_10MHz_High_QPSK_50@0(30MHz~27.55GHz)




ProjectNo. RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:07:15

15MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:07:38

15MHz_Low_QPSK_75@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:07:57

15MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:08:18

15MHz_Middle_QPSK_75@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:08:38

15MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:08:58

15MHz_High_QPSK_75@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:09:18

20MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:09:40

20MHz_Low_QPSK_100@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:10:00

20MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:10:21

20MHz_Middle_QPSK_100@0(30MHz~27.55GHz)




ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:10:42

20MHz_High_QPSK_1@0(30MHz~27.55GHz)



ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:11:03

20MHz_High_QPSK_100@0(30MHz~27.55GHz)



ProjectNo.:RKSA240808001 Tester:Neil Zhou
Date: 20.FEB.2025 17:11:23

***** END *****