







Band4-20MHz-16QAM-20050-1RB#0



Band4-20MHz-16QAM-20050-100RB#0




Band4-20MHz-16QAM-20175-1RB#0




Band4-20MHz-16QAM-20175-100RB#0



Band4-20MHz-16QAM-20300-1RB#0



Band4-20MHz-16QAM-20300-100RB#0



## Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com

## Appendix C: 26dB Bandwidth and Occupied Bandwidth

### Test Result

| Band  | Bandwidth | Modulation | Channel | RB Configuration | Occupied Bandwidth (MHz) | 26dB Bandwidth (MHz) | Verdict |
|-------|-----------|------------|---------|------------------|--------------------------|----------------------|---------|
| Band4 | 1.4MHz    | QPSK       | 19957   | 6RB#0            | 1.0911                   | 1.273                | PASS    |
| Band4 | 1.4MHz    | QPSK       | 20175   | 6RB#0            | 1.0907                   | 1.268                | PASS    |
| Band4 | 1.4MHz    | QPSK       | 20393   | 6RB#0            | 1.0964                   | 1.267                | PASS    |
| Band4 | 1.4MHz    | 16QAM      | 19957   | 6RB#0            | 1.0886                   | 1.241                | PASS    |
| Band4 | 1.4MHz    | 16QAM      | 20175   | 6RB#0            | 1.0908                   | 1.263                | PASS    |
| Band4 | 1.4MHz    | 16QAM      | 20393   | 6RB#0            | 1.0903                   | 1.266                | PASS    |
| Band4 | 3MHz      | QPSK       | 19965   | 15RB#0           | 2.6952                   | 2.921                | PASS    |
| Band4 | 3MHz      | QPSK       | 20175   | 15RB#0           | 2.7011                   | 2.916                | PASS    |
| Band4 | 3MHz      | QPSK       | 20385   | 15RB#0           | 2.6967                   | 2.917                | PASS    |
| Band4 | 3MHz      | 16QAM      | 19965   | 15RB#0           | 2.6938                   | 2.907                | PASS    |
| Band4 | 3MHz      | 16QAM      | 20175   | 15RB#0           | 2.6942                   | 2.913                | PASS    |
| Band4 | 3MHz      | 16QAM      | 20385   | 15RB#0           | 2.6967                   | 2.909                | PASS    |
| Band4 | 5MHz      | QPSK       | 19975   | 25RB#0           | 4.5037                   | 4.941                | PASS    |
| Band4 | 5MHz      | QPSK       | 20175   | 25RB#0           | 4.4983                   | 4.882                | PASS    |
| Band4 | 5MHz      | QPSK       | 20375   | 25RB#0           | 4.5023                   | 4.884                | PASS    |
| Band4 | 5MHz      | 16QAM      | 19975   | 25RB#0           | 4.5054                   | 4.895                | PASS    |
| Band4 | 5MHz      | 16QAM      | 20175   | 25RB#0           | 4.5020                   | 4.913                | PASS    |
| Band4 | 5MHz      | 16QAM      | 20375   | 25RB#0           | 4.5123                   | 4.847                | PASS    |
| Band4 | 10MHz     | QPSK       | 20000   | 50RB#0           | 8.9603                   | 9.547                | PASS    |
| Band4 | 10MHz     | QPSK       | 20175   | 50RB#0           | 8.9627                   | 9.550                | PASS    |
| Band4 | 10MHz     | QPSK       | 20350   | 50RB#0           | 8.9611                   | 9.565                | PASS    |
| Band4 | 10MHz     | 16QAM      | 20000   | 50RB#0           | 8.9547                   | 9.529                | PASS    |
| Band4 | 10MHz     | 16QAM      | 20175   | 50RB#0           | 8.9593                   | 9.557                | PASS    |
| Band4 | 10MHz     | 16QAM      | 20350   | 50RB#0           | 8.9490                   | 9.528                | PASS    |
| Band4 | 15MHz     | QPSK       | 20025   | 75RB#0           | 13.425                   | 14.33                | PASS    |
| Band4 | 15MHz     | QPSK       | 20175   | 75RB#0           | 13.431                   | 14.26                | PASS    |
| Band4 | 15MHz     | QPSK       | 20325   | 75RB#0           | 13.451                   | 14.25                | PASS    |
| Band4 | 15MHz     | 16QAM      | 20025   | 75RB#0           | 13.418                   | 14.26                | PASS    |
| Band4 | 15MHz     | 16QAM      | 20175   | 75RB#0           | 13.438                   | 14.27                | PASS    |
| Band4 | 15MHz     | 16QAM      | 20325   | 75RB#0           | 13.439                   | 14.25                | PASS    |
| Band4 | 20MHz     | QPSK       | 20050   | 100RB#0          | 17.878                   | 18.91                | PASS    |
| Band4 | 20MHz     | QPSK       | 20175   | 100RB#0          | 17.894                   | 18.98                | PASS    |
| Band4 | 20MHz     | QPSK       | 20300   | 100RB#0          | 17.908                   | 18.96                | PASS    |

### Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

|       |       |       |       |         |        |       |      |
|-------|-------|-------|-------|---------|--------|-------|------|
| Band4 | 20MHz | 16QAM | 20050 | 100RB#0 | 17.860 | 18.93 | PASS |
| Band4 | 20MHz | 16QAM | 20175 | 100RB#0 | 17.911 | 18.98 | PASS |
| Band4 | 20MHz | 16QAM | 20300 | 100RB#0 | 17.926 | 18.98 | PASS |

**Shenzhen Anbotech Compliance Laboratory Limited**

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community,  
Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: [service@anbotech.com](mailto:service@anbotech.com)




Hotline

400-003-0500


[www.anbotech.com](http://www.anbotech.com)

## Test Graphs

Band4-1.4MHz-QPSK-19957-6RB#0



Band4-1.4MHz-QPSK-20175-6RB#0



Band4-1.4MHz-QPSK-20393-6RB#0

## Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com



Band4-1.4MHz-16QAM-19957-6RB#0



Band4-1.4MHz-16QAM-20175-6RB#0



Band4-1.4MHz-16QAM-20393-6RB#0

## Shenzhen Anbotech Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com


Hotline  
400-003-0500  
www.anbotech.com



Band4-3MHz-QPSK-19965-15RB#0



Band4-3MHz-QPSK-20175-15RB#0



Band4-3MHz-QPSK-20385-15RB#0

## Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com


Hotline  
400-003-0500  
www.anbotek.com



Band4-3MHz-16QAM-19965-15RB#0



Band4-3MHz-16QAM-20175-15RB#0



Band4-3MHz-16QAM-20385-15RB#0

**Shenzhen Anbotek Compliance Laboratory Limited**

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.


Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com




Hotline

400-003-0500


www.anbotek.com



Band4-5MHz-QPSK-19975-25RB#0



Band4-5MHz-QPSK-20175-25RB#0



Band4-5MHz-QPSK-20375-25RB#0

## Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com


Hotline  
400-003-0500  
www.anbotek.com



Band4-5MHz-16QAM-19975-25RB#0



Band4-5MHz-16QAM-20175-25RB#0




Band4-5MHz-16QAM-20375-25RB#0

## Shenzhen Anbotech Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com

Hotline  
400-003-0500  
www.anbotech.com



Band4-10MHz-QPSK-20000-50RB#0



Band4-10MHz-QPSK-20175-50RB#0



Band4-10MHz-QPSK-20350-50RB#0

## Shenzhen Anbotech Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com

Hotline  
400-003-0500  
www.anbotech.com



Band4-10MHz-16QAM-20000-50RB#0



Band4-10MHz-16QAM-20175-50RB#0



Band4-10MHz-16QAM-20350-50RB#0

## Shenzhen Anbotech Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com


Hotline  
400-003-0500  
www.anbotech.com



Band4-15MHz-QPSK-20025-75RB#0



Band4-15MHz-QPSK-20175-75RB#0



Band4-15MHz-QPSK-20325-75RB#0

## Shenzhen Anbotech Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com


Hotline  
400-003-0500  
www.anbotech.com



Band4-15MHz-16QAM-20025-75RB#0



Band4-15MHz-16QAM-20175-75RB#0



Band4-15MHz-16QAM-20325-75RB#0

**Shenzhen Anbotech Compliance Laboratory Limited**

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.


Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com




Hotline

400-003-0500

www.anbotech.com



Band4-20MHz-QPSK-20050-100RB#0



Band4-20MHz-QPSK-20175-100RB#0



Band4-20MHz-QPSK-20300-100RB#0

## Shenzhen Anbotech Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com

Hotline  
400-003-0500  
www.anbotech.com



Band4-20MHz-16QAM-20050-100RB#0



Band4-20MHz-16QAM-20175-100RB#0



Band4-20MHz-16QAM-20300-100RB#0

## Shenzhen Anbotech Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotech.com

Hotline  
400-003-0500  
www.anbotech.com

**Shenzhen Anbotek Compliance Laboratory Limited**

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

## Appendix D: Band Edge

### Test Result

| Band  | Bandwidth | Modulation | Channel | RB Configuration | Result(dBm) | Verdict |
|-------|-----------|------------|---------|------------------|-------------|---------|
| Band4 | 1.4MHz    | QPSK       | 19957   | 1RB#0            | -18.30      | PASS    |
| Band4 | 1.4MHz    | QPSK       | 19957   | 1RB#5            | -36.29      | PASS    |
| Band4 | 1.4MHz    | QPSK       | 19957   | 6RB#0            | -20.76      | PASS    |
| Band4 | 1.4MHz    | QPSK       | 20393   | 1RB#0            | -40.53      | PASS    |
| Band4 | 1.4MHz    | QPSK       | 20393   | 1RB#5            | -16.33      | PASS    |
| Band4 | 1.4MHz    | QPSK       | 20393   | 6RB#0            | -22.24      | PASS    |
| Band4 | 1.4MHz    | 16QAM      | 19957   | 1RB#0            | -19.16      | PASS    |
| Band4 | 1.4MHz    | 16QAM      | 19957   | 1RB#5            | -38.18      | PASS    |
| Band4 | 1.4MHz    | 16QAM      | 19957   | 6RB#0            | -24.54      | PASS    |
| Band4 | 1.4MHz    | 16QAM      | 20393   | 1RB#0            | -40.36      | PASS    |
| Band4 | 1.4MHz    | 16QAM      | 20393   | 1RB#5            | -15.59      | PASS    |
| Band4 | 1.4MHz    | 16QAM      | 20393   | 6RB#0            | -22.74      | PASS    |
| Band4 | 3MHz      | QPSK       | 19965   | 1RB#0            | -14.29      | PASS    |
| Band4 | 3MHz      | QPSK       | 19965   | 1RB#14           | -41.80      | PASS    |
| Band4 | 3MHz      | QPSK       | 19965   | 15RB#0           | -21.31      | PASS    |
| Band4 | 3MHz      | QPSK       | 20385   | 1RB#0            | -40.06      | PASS    |
| Band4 | 3MHz      | QPSK       | 20385   | 1RB#14           | -14.11      | PASS    |
| Band4 | 3MHz      | QPSK       | 20385   | 15RB#0           | -20.96      | PASS    |
| Band4 | 3MHz      | 16QAM      | 19965   | 1RB#0            | -14.24      | PASS    |
| Band4 | 3MHz      | 16QAM      | 19965   | 1RB#14           | -42.64      | PASS    |
| Band4 | 3MHz      | 16QAM      | 19965   | 15RB#0           | -22.38      | PASS    |
| Band4 | 3MHz      | 16QAM      | 20385   | 1RB#0            | -40.73      | PASS    |
| Band4 | 3MHz      | 16QAM      | 20385   | 1RB#14           | -15.47      | PASS    |
| Band4 | 3MHz      | 16QAM      | 20385   | 15RB#0           | -21.02      | PASS    |
| Band4 | 5MHz      | QPSK       | 19975   | 1RB#0            | -13.41      | PASS    |
| Band4 | 5MHz      | QPSK       | 19975   | 1RB#24           | -49.73      | PASS    |
| Band4 | 5MHz      | QPSK       | 19975   | 25RB#0           | -20.01      | PASS    |
| Band4 | 5MHz      | QPSK       | 20375   | 1RB#0            | -48.23      | PASS    |
| Band4 | 5MHz      | QPSK       | 20375   | 1RB#24           | -14.94      | PASS    |
| Band4 | 5MHz      | QPSK       | 20375   | 25RB#0           | -21.31      | PASS    |
| Band4 | 5MHz      | 16QAM      | 19975   | 1RB#0            | -14.28      | PASS    |
| Band4 | 5MHz      | 16QAM      | 19975   | 1RB#24           | -50.02      | PASS    |
| Band4 | 5MHz      | 16QAM      | 19975   | 25RB#0           | -22.08      | PASS    |
| Band4 | 5MHz      | 16QAM      | 20375   | 1RB#0            | -46.71      | PASS    |
| Band4 | 5MHz      | 16QAM      | 20375   | 1RB#24           | -14.62      | PASS    |

#### Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

|       |       |       |       |         |        |      |
|-------|-------|-------|-------|---------|--------|------|
| Band4 | 5MHz  | 16QAM | 20375 | 25RB#0  | -22.51 | PASS |
| Band4 | 10MHz | QPSK  | 20000 | 1RB#0   | -21.81 | PASS |
| Band4 | 10MHz | QPSK  | 20000 | 1RB#49  | -46.89 | PASS |
| Band4 | 10MHz | QPSK  | 20000 | 50RB#0  | -25.49 | PASS |
| Band4 | 10MHz | QPSK  | 20350 | 1RB#0   | -43.52 | PASS |
| Band4 | 10MHz | QPSK  | 20350 | 1RB#49  | -21.33 | PASS |
| Band4 | 10MHz | QPSK  | 20350 | 50RB#0  | -26.29 | PASS |
| Band4 | 10MHz | 16QAM | 20000 | 1RB#0   | -21.62 | PASS |
| Band4 | 10MHz | 16QAM | 20000 | 1RB#49  | -46.02 | PASS |
| Band4 | 10MHz | 16QAM | 20000 | 50RB#0  | -27.32 | PASS |
| Band4 | 10MHz | 16QAM | 20350 | 1RB#0   | -44.21 | PASS |
| Band4 | 10MHz | 16QAM | 20350 | 1RB#49  | -21.80 | PASS |
| Band4 | 10MHz | 16QAM | 20350 | 50RB#0  | -28.11 | PASS |
| Band4 | 15MHz | QPSK  | 20025 | 1RB#0   | -19.20 | PASS |
| Band4 | 15MHz | QPSK  | 20025 | 1RB#74  | -45.10 | PASS |
| Band4 | 15MHz | QPSK  | 20025 | 75RB#0  | -26.58 | PASS |
| Band4 | 15MHz | QPSK  | 20325 | 1RB#0   | -42.13 | PASS |
| Band4 | 15MHz | QPSK  | 20325 | 1RB#74  | -20.48 | PASS |
| Band4 | 15MHz | QPSK  | 20325 | 75RB#0  | -28.20 | PASS |
| Band4 | 15MHz | 16QAM | 20025 | 1RB#0   | -20.15 | PASS |
| Band4 | 15MHz | 16QAM | 20025 | 1RB#74  | -45.55 | PASS |
| Band4 | 15MHz | 16QAM | 20025 | 75RB#0  | -28.72 | PASS |
| Band4 | 15MHz | 16QAM | 20325 | 1RB#0   | -42.52 | PASS |
| Band4 | 15MHz | 16QAM | 20325 | 1RB#74  | -21.05 | PASS |
| Band4 | 15MHz | 16QAM | 20325 | 75RB#0  | -29.60 | PASS |
| Band4 | 20MHz | QPSK  | 20050 | 1RB#0   | -20.82 | PASS |
| Band4 | 20MHz | QPSK  | 20050 | 1RB#99  | -47.40 | PASS |
| Band4 | 20MHz | QPSK  | 20050 | 100RB#0 | -28.68 | PASS |
| Band4 | 20MHz | QPSK  | 20300 | 1RB#0   | -47.42 | PASS |
| Band4 | 20MHz | QPSK  | 20300 | 1RB#99  | -22.16 | PASS |
| Band4 | 20MHz | QPSK  | 20300 | 100RB#0 | -29.18 | PASS |
| Band4 | 20MHz | 16QAM | 20050 | 1RB#0   | -20.66 | PASS |
| Band4 | 20MHz | 16QAM | 20050 | 1RB#99  | -47.53 | PASS |
| Band4 | 20MHz | 16QAM | 20050 | 100RB#0 | -29.39 | PASS |
| Band4 | 20MHz | 16QAM | 20300 | 1RB#0   | -47.50 | PASS |
| Band4 | 20MHz | 16QAM | 20300 | 1RB#99  | -21.23 | PASS |
| Band4 | 20MHz | 16QAM | 20300 | 100RB#0 | -29.56 | PASS |

## Test Graphs

Band4-1.4MHz-QPSK-19957-1RB#0

### Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com



Hotline

400-003-0500

www.anbotek.com



Band4-1.4MHz-QPSK-19957-1RB#5



Band4-1.4MHz-QPSK-19957-6RB#0



Band4-1.4MHz-QPSK-20393-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com



Band4-1.4MHz-QPSK-20393-1RB#5



Band4-1.4MHz-QPSK-20393-6RB#0



Band4-1.4MHz-16QAM-19957-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com



Band4-1.4MHz-16QAM-19957-1RB#5



Band4-1.4MHz-16QAM-19957-6RB#0



Band4-1.4MHz-16QAM-20393-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com



Band4-1.4MHz-16QAM-20393-1RB#5



Band4-1.4MHz-16QAM-20393-6RB#0




Band4-3MHz-QPSK-19965-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com


Hotline  
400-003-0500  
www.anbotek.com



Band4-3MHz-QPSK-19965-1RB#14



Band4-3MHz-QPSK-19965-15RB#0




Band4-3MHz-QPSK-20385-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com



Band4-3MHz-QPSK-20385-1RB#14



Band4-3MHz-QPSK-20385-15RB#0




Band4-3MHz-16QAM-19965-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com



Band4-3MHz-16QAM-19965-1RB#14



Band4-3MHz-16QAM-19965-15RB#0




Band4-3MHz-16QAM-20385-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com



Band4-3MHz-16QAM-20385-1RB#14



Band4-3MHz-16QAM-20385-15RB#0




Band4-5MHz-QPSK-19975-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com



Band4-5MHz-QPSK-19975-1RB#24



Band4-5MHz-QPSK-19975-25RB#0




Band4-5MHz-QPSK-20375-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com



Band4-5MHz-QPSK-20375-1RB#24



Band4-5MHz-QPSK-20375-25RB#0




Band4-5MHz-16QAM-19975-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com



Band4-5MHz-16QAM-19975-1RB#24



Band4-5MHz-16QAM-19975-25RB#0




Band4-5MHz-16QAM-20375-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited


Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com



Band4-5MHz-16QAM-20375-1RB#24



Band4-5MHz-16QAM-20375-25RB#0



Band4-10MHz-QPSK-20000-1RB#0

## Shenzhen Anbotek Compliance Laboratory Limited

Address: 1/F., Building D, Sogood Science and Technology Park, Sanwei Community, Hangcheng Street, Bao'an District, Shenzhen, Guangdong, China.

Tel: (86) 755-26066440 Fax: (86) 755-26014772 Email: service@anbotek.com

Hotline  
400-003-0500  
www.anbotek.com