

**Chengdu Tops Technology Co.,Ltd.**

No. 915, Floor 9, Building 1, No. 1388, Middle Section, Tianfu Avenue, High-Tech Area,  
Chengdu, China

---

**Date:** 2025-9-10

**FCC ID:** 2A3DK-DSPH

**Model Number:** DSPH, DSPF, DSPW, DSPH-6L-2.5LV, DSPF-01, DSPF-02, DSPF-03, DSPF-04, DSPF-05, DSPF-06, DSPF-07, DSPF-08, DSPF-09, DSPF-10, DSPH-01, DSPH-02, DSPH-03, DSPH-04, DSPH-05, DSPH-06, DSPH-07, DSPH-08, DSPH-09, DSPH-10, DSPW-01, DSPW-02, DSPW-03, DSPW-04, DSPW-05, DSPW-06, DSPW-07, DSPW-08, DSPW-09, DSPW-10, DSPH-6L-2.5LV1P, DSPH-6L-2.5LV2P, DSPH-6L-2.5LV3P, DSPH-6L-2.5LV4P, DSPH-6L-2.5LV5P, DSPH-6L-2.5LV6P, DSPH-6L-2.5LV7P, DSPH-6L-2.5LV8P, DSPH-6L-2.5LV9P, DSPH-6L-2.5LV10P

To:


Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, MD

To Whom It May Concern,

We, **Chengdu Tops Technology Co.,Ltd.**, declare that this EUT (FCC ID: **2A3DK-DSPH**) doesn't have Ad Hoc mode function on "non-US/Canada frequencies". In addition. The frequency selection feature is disabled by firmware for devices marked to the US/Canada. For DTS part of this device, only channels 1-11 will be used in North America, Country code selection is disabled.

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely,



Name/Title: Fan Xing/Manager  
Company: Chengdu Tops Technology Co.,Ltd.  
Address: No. 915, Floor 9, Building 1, No. 1388, Middle Section, Tianfu Avenue, High-Tech Area, Chengdu, China  
Phone: 15889312153  
Fax: 15889312153  
E-Mail: 461305952@qq.com