


Autotek Industrial Limited
1318-19, 13/F, Hollywood Plaza, 610 Nathan Road, Mongkok, Kowloon, Hong-Kong, China.

F720A Tune up Procedure

I would like to confirm this device does not have tune up information, because the tune up is fixed by the manufacturer.
Therefore, the user cannot tune up the device.

Conducted average power range is below:

WCDMA Band 2		WCDMA Band 5
Mode	Maximum Target Value	Maximum Target Value
RMC 12.2kbps	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
RMC 64kbps	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
RMC 144kbps	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
RMC 384kbps	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
HSDPA Sub-test 1	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
HSDPA Sub-test 2	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
HSDPA Sub-test 3	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
HSDPA Sub-test 4	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
HSUPA Sub-test 1	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
HSUPA Sub-test 2	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
HSUPA Sub-test 3	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0
HSUPA Sub-test 4	24.0dBm $\pm$ 1.0	23.0dBm $\pm$ 1.0



Client's name / title : LucienLuo /Manager

Contact information / address: 1318-19, 13/F, Hollywood Plaza, 610 Nathan Road, Mongkok, Kowloon,
Hong-Kong, China.