



Report No.: AAEMT/EMC/220321-01-05

26dB BW 802.11ax40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-05

26dB BW 802.11ax80


Channel: 42




Report No.: AAEMT/EMC/220321-01-05

Test plots as followed: 5GS_3

26dB BW 802.11a
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-05


Channel: 48




Report No.: AAEMT/EMC/220321-01-05

26dB BW 802.11n20


Channel: 36



Channel: 44




Channel: 48




Report No.: AAEMT/EMC/220321-01-05

26dB BW 802.11n40

Channel: 38



Channel: 46



Report No.: AAEMT/EMC/220321-01-05

26dB BW 802.11ac20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-05


Channel: 48




Report No.: AAEMT/EMC/220321-01-05

26dB BW 802.11ac40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-05

26dB BW 802.11ac80

Channel: 42




Report No.: AAEMT/EMC/220321-01-05

26dB BW 802.11ax20


Channel: 36



Channel: 44




Channel: 48




Report No.: AAEMT/EMC/220321-01-05

26dB BW 802.11ax40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-05

26dB BW 802.11ax80


Channel: 42




Test plots as followed: 5GM_0

6dB BW 802.11a

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac80


Channel: 155




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ax20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-05


6dB BW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-01-05

Test plots as followed: 5GM_1

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac40
Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-05


6dB BW 802.11ac80
Channel: 155



6dB BW 802.11ax20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ax80


Channel: 155




Report No.: AAEMT/EMC/220321-01-05

Test plots as followed: 5GM_2

6dB BW 802.11a
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11n20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac80


Channel: 155




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ax20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ax40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-01-05


Test plots as followed: 5GM_3

6dB BW 802.11a

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac40
Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ac80
Channel: 155




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ax20
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ax40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-05

6dB BW 802.11ax80
Channel: 155



Report No.: AAEMT/EMC/220321-01-05


Test plots as followed: 5GS_0

99% OBW 802.11a

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-05

Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n20
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-05


Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n40

Channel: 38




Channel: 46




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac20
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-05


Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-05


99% OBW 802.11ac80

Channel: 42




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax20
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-05

Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax40
Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax80

Channel: 42




Report No.: AAEMT/EMC/220321-01-05


Test plots as followed: 5GM_0

99% OBW 802.11a

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n20
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n40
Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel:165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac40

Channel:151




Channel:159



Report No.: AAEMT/EMC/220321-01-05


99% OBW 802.11ac80

Channel:155




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax20
Channel:149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-01-05


Test plots as followed: 5GS_1

99% OBW 802.11a

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-05

Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n20
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-05


Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n40

Channel: 38




Channel: 46




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac20
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-05

Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac40
Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-05


99% OBW 802.11ac80
Channel: 42




Date: 30, MAR, 2022 00:09:41

Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax20
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-05

Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax40
Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax80
Channel: 42




Report No.: AAEMT/EMC/220321-01-05


Test plots as followed: 5GM_1

99% OBW 802.11a

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n40
Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel:165



Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac40

Channel:151




Channel:159



Report No.: AAEMT/EMC/220321-01-05


99% OBW 802.11ac80
Channel:155




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax20

Channel:149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax80

Channel: 155




Report No.: AAEMT/EMC/220321-01-05


Test plots as followed: 5GS_2

99% OBW 802.11a

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-05

Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n20
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-05

Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n40
Channel: 38




Channel: 46




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac20
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-05


Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac80


Channel: 42




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax20

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-05

Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax40
Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax80

Channel: 42




Report No.: AAEMT/EMC/220321-01-05


Test plots as followed: 5GM_2

99% OBW 802.11a

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n40
Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-05


Channel: 165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ac40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-05


99% OBW 802.11ac80

Channel: 155




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax20
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-05

Channel: 165




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11ax40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-05


99% OBW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-01-05

Test plots as followed: 5GS_3

99% OBW 802.11a
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-05

Channel: 48




Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n20
Channel: 36



Channel: 44



Report No.: AAEMT/EMC/220321-01-05


Channel: 48



Report No.: AAEMT/EMC/220321-01-05

99% OBW 802.11n40

Channel: 38



Channel: 46

