



Report No.: AAEMT/EMC/220321-01-06

26dB BW 802.11ax40

Channel: 38




Channel: 46




26dB BW 802.11ax80

Channel: 42




Test plots as followed: 5GS_3


26dB BW 802.11a
Channel: 36



Channel: 44




Channel: 48




Report No.: AAEMT/EMC/220321-01-06

26dB BW 802.11n20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-06


Channel: 48




Report No.: AAEMT/EMC/220321-01-06

26dB BW 802.11n40

Channel: 38



Channel: 46




Report No.: AAEMT/EMC/220321-01-06

26dB BW 802.11ac20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-06


Channel: 48




Report No.: AAEMT/EMC/220321-01-06

26dB BW 802.11ac40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-06

26dB BW 802.11ac80

Channel: 42




Report No.: AAEMT/EMC/220321-01-06

26dB BW 802.11ax20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-06


Channel: 48




Report No.: AAEMT/EMC/220321-01-06

26dB BW 802.11ax40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-06

26dB BW 802.11ax80


Channel: 42




Test plots as followed: 5GM_0

6dB BW 802.11a

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06


Channel: 165



6dB BW 802.11ac40
Channel: 151




Channel: 159



6dB BW 802.11ac80


Channel: 155




Date: 2.APR.2022 09:44:13

Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ax20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06


6dB BW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-01-06

Test plots as followed: 5GM_1

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11n20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06

Channel: 165




6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06

Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ac40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06


6dB BW 802.11ac80
Channel: 155




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ax20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06


6dB BW 802.11ax80

Channel: 155




Test plots as followed: 5GM_2

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06

Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ac40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ac80


Channel: 155




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ax20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06


6dB BW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-01-06

Test plots as followed: 5GM_3

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06

Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ac40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ac80


Channel: 155




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ax20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06

Channel: 165




Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ax40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06

6dB BW 802.11ax80

Channel: 155



Report No.: AAEMT/EMC/220321-01-06


Test plots as followed: 5GS_0

99% OBW 802.11a


Channel: 36



Channel: 44




Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n20
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-06

Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n40
Channel: 38




Channel: 46




Report No.: AAEMT/EMC/220321-01-06


99% OBW 802.11ac20
Channel: 36



Channel: 44




Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-06


99% OBW 802.11ac80

Channel: 42




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax20
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-06

Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax40
Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax80


Channel: 42




Report No.: AAEMT/EMC/220321-01-06

Test plots as followed: 5GM_0

99% OBW 802.11a
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06

Channel: 165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n20
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06

Channel: 165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n40
Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel:165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac40

Channel:151




Channel:159



99% OBW 802.11ac80


Channel:155




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax20

Channel:149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06


99% OBW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-01-06

Test plots as followed: 5GS_1

99% OBW 802.11a
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-06


Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-06


Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n40

Channel: 38




Channel: 46




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac20
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-06


Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac40

Channel: 38




Channel: 46




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac80
Channel: 42




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax20
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-06

Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax40
Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax80


Channel: 42




Report No.: AAEMT/EMC/220321-01-06

Test plots as followed: 5GM_1

99% OBW 802.11a
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06

Channel: 165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n20
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06

Channel: 165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n40
Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel:165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac40

Channel:151




Channel:159



Report No.: AAEMT/EMC/220321-01-06


99% OBW 802.11ac80
Channel:155




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax20

Channel:149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax80

Channel: 155




Report No.: AAEMT/EMC/220321-01-06


Test plots as followed: 5GS_2

99% OBW 802.11a

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-06


Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-06


Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n40

Channel: 38




Channel: 46




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac20

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-01-06

Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac40
Channel: 38




Channel: 46




99% OBW 802.11ac80

Channel: 42




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax20
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-06


Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-01-06


99% OBW 802.11ax80
Channel: 42




Report No.: AAEMT/EMC/220321-01-06

Test plots as followed: 5GM_2

99% OBW 802.11a
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-01-06

Channel: 165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ac80


Channel: 155




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-01-06


Channel: 165




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-01-06


99% OBW 802.11ax80
Channel: 155




Test plots as followed: 5GS_3

99% OBW 802.11a

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-01-06

Channel: 48




Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n20


Channel: 36



Channel: 44




Channel: 48



Report No.: AAEMT/EMC/220321-01-06

99% OBW 802.11n40

Channel: 38



Channel: 46

