

Date: 2022-4-20


To:
Federal Communications Commission
Authorization and Evaluation Division
Equipment Authorization Branch
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern,

Original FCC ID: 2A4GHBN590131233028; Model Number: AMT-2IN1-BN59-01311B-bl, AMT-2IN1-BN59-01312B-vc, AMT-2IN1-BN59-01311G-bl, AMT-2IN1-BN59-01312H-vc, AMT-2IN1-BN59-01329B-vc, AMT-2IN1-BN59-01330B-blvc, AMT-2IN1-BN59-01329A-BT, AMT-2IN1-BN59-01330A-01329A-all, AMT-2IN1-BN59-01330A-voice, AMT-2IN1-BN59-01357A-bl, AMT-2IN1-BN59-01357A-vc, AMT-2IN1-BN59-01357A-blt-VIC, AMT-2IN1-BN59-01357A-blue-vc-Q80A, AMT-2IN1-BN59-01357B-BUT, AMT-2IN1-BN59-01357B-VOC, AMT-2IN1-BN59-01357B-BL-VC, AMT-2IN1-BN59-01357B-BLue-voice, AMT-2IN1-BN59-01357A-01357B-BL-VC-all, AMT-2IN1-BN59-01363L-bl, AMT-2IN1-BN59-01363C-vc, AMT-BN59-01311G-blvc, AMT-BN59-01312A-BLU-VOICE, AMT-SAM-BN59-01312A-BLUE, AMT-SAMVOICE-BN59-01312A, AMT-SAMS-BLUE-TOOTH-BN59-01312G, AMT-VOICE-BN59-01312G, AMT-BN59-01312M-SAM-VOICE, AMT-BN59-01312M-BLUETO-OTH, AMT-SAM-BLUE-BN59-01312M, AMT-VOICE-BN59-01312M-SAM, AMT-SAM-VOICE-BN59-01312QWHITE, AMT-BN59-01312R-voi-wh, AMT-BN59-01327B-blvc-gx, AMT-BN59-01329H-voi, AMT-BN59-01330H-BLUE, AMT-BN59-01330H-VOICE-CA, AMT-BN59-01350B-vce, AMT-BN59-01357Dbtve, AMT-BN59-01357E-blvce, AMT-BN59-01363J-blce, AMT-3IN1-BN59-01329B-bl, AMT-3IN1-BN59-01328A-vc, AMT-3IN1-BN59-01330B-blvc
New FCC ID: 2A42BBN59-01357A; Model Number: WL-BN59-01357A-01357B-MIC-S1-210813, WL-RH-ERF3A69-ORI-DHF-S2, WL-DISH-52-DHF-S1, WL-ERF-Serier

This is to advise and officially, that we, **WINFLIKE INC** hereby declare that the product name is same and only FCC ID and model number difference as market requirement;
The original test results continue to be representative of and applicable to the equipment of the new FCC ID;
If you have any query, please feel free to contact me.

Sincerely,



Client's name / title : DONGFANG PENG/Manager

Company: WINFLIKE INC

address : 680 S COLORADO BLVD GLENDALE Colorado United States

WINFLIKE INC

680 S COLORADO BLVD GLENDALE Colorado United States

Tel: (139) 620-0247 35 Fax: (139) 620-0247

Email: handy20017861@hotmail.com