






Band2-3MHz-16QAM-18615-1-0-Low-5000-12000--57.53-PASS



Band2-3MHz-16QAM-18615-1-0-Low-12000-26500--42.39-PASS



Band2-3MHz-16QAM-18900-1-0-Low-30-1000--35.67-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-3MHz-16QAM-18900-1-0-Low-1000-5000--38.48-PASS



Band2-3MHz-16QAM-18900-1-0-Low-5000-12000--57.46-PASS



Band2-3MHz-16QAM-18900-1-0-Low-12000-26500--42.75-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-3MHz-16QAM-19185-1-0-High-30-1000--35.87-PASS




Band2-3MHz-16QAM-19185-1-0-High-1000-5000--38.61-PASS




Band2-3MHz-16QAM-19185-1-0-High-5000-12000--57.48-PASS






Band2-3MHz-16QAM-19185-1-0-High-12000-26500--42.44-PASS




Band2-5MHz-QPSK-18625-1-0-Low-30-1000--35.19-PASS




Band2-5MHz-QPSK-18625-1-0-Low-1000-5000--37.06-PASS






Band2-5MHz-QPSK-18625-1-0-Low-5000-12000--57.46-PASS




Band2-5MHz-QPSK-18625-1-0-Low-12000-26500--42.66-PASS




Band2-5MHz-QPSK-18900-1-0-Low-30-1000--34.82-PASS






Band2-5MHz-QPSK-18900-1-0-Low-1000-5000--36.8-PASS




Band2-5MHz-QPSK-18900-1-0-Low-5000-12000--57.4-PASS




Band2-5MHz-QPSK-18900-1-0-Low-12000-26500--42.58-PASS






Band2-5MHz-QPSK-19175-1-0-High-30-1000--35.75-PASS



Band2-5MHz-QPSK-19175-1-0-High-1000-5000--38.14-PASS



Band2-5MHz-QPSK-19175-1-0-High-5000-12000--57.42-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-5MHz-QPSK-19175-1-0-High-12000-26500--42.54-PASS




Band2-5MHz-16QAM-18625-1-0-Low-30-1000--34.8-PASS




Band2-5MHz-16QAM-18625-1-0-Low-1000-5000--38.37-PASS






Band2-5MHz-16QAM-18625-1-0-Low-5000-12000--57.4-PASS




Band2-5MHz-16QAM-18625-1-0-Low-12000-26500--42.79-PASS




Band2-5MHz-16QAM-18900-1-0-Low-30-1000--34.83-PASS






Band2-5MHz-16QAM-18900-1-0-Low-1000-5000--38.65-PASS




Band2-5MHz-16QAM-18900-1-0-Low-5000-12000--57.44-PASS




Band2-5MHz-16QAM-18900-1-0-Low-12000-26500--42.67-PASS






Band2-5MHz-16QAM-19175-1-0-High-30-1000--35.83-PASS




Band2-5MHz-16QAM-19175-1-0-High-1000-5000--38.26-PASS




Band2-5MHz-16QAM-19175-1-0-High-5000-12000--57.3-PASS






Band2-5MHz-16QAM-19175-1-0-High-12000-26500--42.64-PASS




Band2-10MHz-QPSK-18650-1-0-Low-30-1000--35.45-PASS




Band2-10MHz-QPSK-18650-1-0-Low-1000-5000--38.43-PASS






Band2-10MHz-QPSK-18650-1-0-Low-5000-12000--57.44-PASS



Band2-10MHz-QPSK-18650-1-0-Low-12000-26500--42.69-PASS



Band2-10MHz-QPSK-18900-1-0-Low-30-1000--35.41-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-10MHz-QPSK-18900-1-0-Low-1000-5000--38.59-PASS




Band2-10MHz-QPSK-18900-1-0-Low-5000-12000--57.2-PASS




Band2-10MHz-QPSK-18900-1-0-Low-12000-26500--42.62-PASS






Band2-10MHz-QPSK-19150-1-0-High-30-1000--35.76-PASS



Band2-10MHz-QPSK-19150-1-0-High-1000-5000--38.57-PASS



Band2-10MHz-QPSK-19150-1-0-High-5000-12000--57.53-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-10MHz-QPSK-19150-1-0-High-12000-26500--42.48-PASS




Band2-10MHz-16QAM-18650-1-0-Low-30-1000--34.86-PASS




Band2-10MHz-16QAM-18650-1-0-Low-1000-5000--38.66-PASS






Band2-10MHz-16QAM-18650-1-0-Low-5000-12000--57.41-PASS




Band2-10MHz-16QAM-18650-1-0-Low-12000-26500--42.71-PASS




Band2-10MHz-16QAM-18900-1-0-Low-30-1000--34.69-PASS






Band2-10MHz-16QAM-18900-1-0-Low-1000-5000--38.31-PASS




Band2-10MHz-16QAM-18900-1-0-Low-5000-12000--57.4-PASS




Band2-10MHz-16QAM-18900-1-0-Low-12000-26500--42.6-PASS






Band2-10MHz-16QAM-19150-1-0-High-30-1000--35.73-PASS



Band2-10MHz-16QAM-19150-1-0-High-1000-5000--38.02-PASS



Band2-10MHz-16QAM-19150-1-0-High-5000-12000--57.53-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-10MHz-16QAM-19150-1-0-High-12000-26500--42.78-PASS



Band2-15MHz-QPSK-18675-1-0-Low-30-1000--35.54-PASS



Band2-15MHz-QPSK-18675-1-0-Low-1000-5000--38.22-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-15MHz-QPSK-18675-1-0-Low-5000-12000--57.38-PASS



Band2-15MHz-QPSK-18675-1-0-Low-12000-26500--42.7-PASS



Band2-15MHz-QPSK-18900-1-0-Low-30-1000--35.97-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-15MHz-QPSK-18900-1-0-Low-1000-5000--37-PASS



Band2-15MHz-QPSK-18900-1-0-Low-5000-12000--57.52-PASS



Band2-15MHz-QPSK-18900-1-0-Low-12000-26500--42.78-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-15MHz-QPSK-19125-1-0-High-30-1000--34.87-PASS



Band2-15MHz-QPSK-19125-1-0-High-1000-5000--38.44-PASS



Band2-15MHz-QPSK-19125-1-0-High-5000-12000--57.48-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-15MHz-QPSK-19125-1-0-High-12000-26500--42.77-PASS



Band2-15MHz-16QAM-18675-1-0-Low-30-1000--33.92-PASS



Band2-15MHz-16QAM-18675-1-0-Low-1000-5000--38.06-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-15MHz-16QAM-18675-1-0-Low-5000-12000--57.51-PASS



Band2-15MHz-16QAM-18675-1-0-Low-12000-26500--42.75-PASS



Band2-15MHz-16QAM-18900-1-0-Low-30-1000--35.32-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band2-15MHz-16QAM-18900-1-0-Low-1000-5000--38.51-PASS



Band2-15MHz-16QAM-18900-1-0-Low-5000-12000--57.5-PASS



Band2-15MHz-16QAM-18900-1-0-Low-12000-26500--42.59-PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity