



TrellisWare Technologies Inc.
10641 Scripps Summit Court, Suite 100
San Diego, CA 92131
United States

Date: 11/21/2024

Nemko Canada Inc
303 River Road
Ottawa
K1V 1H2
Canada

ATTN.: Reviewing Engineer

FCC : 2A6X2-950A
IC: 28565-950A
HVINs/Models: ASY0750393 (TW-950), ASY0750394 (TW-900)

We hereby request Family Certification for the above mentioned HVINs/Models based on them being electrically, and physically identical apart from model name/number.

The following table describes the differences between the models. All radio models use the same operating software and core radio module which includes all PHY/MAC/RF Interface circuitry and were tested with the same antenna.

Model Number	Data Interface	Audio Interface	Power Interface	Accessories	Notes
ASY0750393 (TW-950)	USB	Analog PTT	Replaceable battery	Ethernet data interface	Control front panel
ASY0750394 (TW-900)	USB	Analog PTT	Replaceable battery	Ethernet data interface	No front panel

Signed: *Mike Rudeen*

Printed name: Michael Rudeen
Title: Project Engineer
Date: 11/21/2024

When Nothing Else Works™